



report date: 2024-03-29

General information

Make	VOLVO
Model	XC70 D5 R-DESIGN LUX NAV AWD
Colour	Silver
Year of manufacture	2014
Top speed	121 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	212 BHP
Max. torque	440 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 1

Date	2022-03-27
Pictures	24
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-31
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	12
Total items failed	2

MOT #9	2024-03-26 16:44
MOT test number	309924301041
Result	✓ Passed
Next expiry date	2025-03-31

MOT #8	2023-03-21 10:27
MOT test number	331487974950
Result	✓ Passed
Advice	Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #7	2022-04-01 13:51
MOT test number	196906737516
Result	✓ Passed
Advice	Offside Rear tyres wearing unevenly inner edge
Advice	Rear Tyre slightly damaged/cracking or perishing both tyres cracking in tread (5.2.3 (d) (ii))
Advice	Covers and undertrays obscuring components

**MOT #6** 2021-07-17 11:19**MOT test number** 127569234113**Result** ✓ Passed**Advice** Both rear tyres cracking in treads**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #5** 2020-07-21 10:48**MOT test number** 667669110754**Result** ✓ Passed**MOT #4** 2019-11-05 13:10**MOT test number** 104619515028**Result** ✓ Passed**MOT #3** 2018-11-08 12:22**MOT test number** 512053074405**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2017-11-21 13:30**MOT test number** 428153913657**Result** ✓ Passed**Advice** Offside Front worn on inner tread**Advice** Engine and underside covers fitted not allowing full inspection



MOT #1	2017-11-21 10:28
MOT test number	250281280042
Result	✗ Failed
Advice	Offside Front worn on inner tread
Fail	Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
Advice	Engine and underside covers fitted not allowing full inspection
Fail	Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
31 March 2025

Tax status	Valid until 1 July
Days left	62
MOT expiry date	31 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	KN64RYR
Plate since	2019-09-29
Current registration	KN64RYR
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-11-25
Last registration	2024-03-26
Complete history	See info



Registration #1	2014-11-25	26 mi
Registration #2	2017-11-21	30.913 mi
Registration #3	2017-11-21	30.915 mi
Registration #4	2018-11-08	39.143 mi
Registration #5	2019-11-05	46.500 mi
Registration #6	2020-07-21	51.366 mi
Registration #7	2020-09-29	55.277 mi
Registration #8	2020-09-29	55.277 mi
Registration #9	2020-09-29	55.277 mi
Registration #10	2020-09-29	55.277 mi
Registration #11	2020-09-29	55.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2120 mm
Height	1713 mm
Length	4644 mm
Wheel base	2774 mm
Kerb weight	1862 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1522159