





report date: 2024-03-29

General information

Make	SUZUKI
Model	CELERIO SZ4
Colour	Red
Year of manufacture	2018
Top speed	97 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.500 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	54.3 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/11



Internet history

Entry 6

Date 2023-07-24

Pictures 0

Listing price <u>View report</u>

source: carcraft.co.uk

Entry 5

Date 2023-05-08

Pictures (

Listing price <u>View report</u>

source: carcraft.co.uk


Entry 4

Date 2023-03-24

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 3

Date 2023-03-04

Pictures 40

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

CarCheck.co.uk page 2/11

 Date
 2023-03-03

 Pictures
 20


View report



Listing price







source: autotrader.co.uk

Entry 1

Date	2021-01-22
Pictures	10

Listing price <u>View report</u>









source: yesauto.com



MOT history

MOT expiry date	2024-07-11
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	8
Total items failed	3

MOT #5		2023-07-12 21:52
MOT test	number	132306289064
Result		✓ Passed
Next expiry date 202		2024-07-11
Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #4		2023-07-12 21:52
MOT test number		467498042428
Result		× Failed
Advice Nearside Front B	rake pad(s) wearing thin (1.1.13 (a) (ii))	
Pass with rectification	Offside Front Headlamp aim too low and too far to th	e right. (4.1.2 (a))
Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Pass with rectification	Nearside Front Headlamp aim too low and too far to	the right. (4.1.2 (a))

MOT #3	2022-04-11 09:52
MOT test number	944754180248
Result	✓ Passed
Minor Nearside Front Lower Suspension rod ball joint dust cover severely determined (5.3.4 (b) (i)) Minor Offside Front Lower Suspension rod ball joint dust cover severely determined (5.3.4 (b) (i))	-

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #2 2022-04-11 09:52

MOT test number 709807830822

Result X Failed

Minor Nearside Front Lower Suspension rod ball joint dust cover severely deteriorated slight leak off grease (5.3.4 (b) (i))

Pass with rectification Offside Front Outer Headlamp aim too high (4.1.2 (a))

Minor Offside Front Lower Suspension rod ball joint dust cover severely deteriorated slight leak off grease (5.3.4 (b) (i))

MOT #1 2021-03-27 11:37

MOT test number 626719462515

Result \rightarrow Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	11 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
First licence fee (12 months)	£ 165,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners have? Check it in the premium report and see all owner registrations. Download the full re		<i< td=""></i<>

	More info	>
Plate changes See in this check if this SUZUKI had different number plates.		
Number of plates		,
Correct registration	UK NE	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2018-04-17
Last registration	2023-07-12
Complete history	See info



Registration #1	2018-04-17	14 mi
Registration #2		11.777 es
Registration #3	2021-03-27	6.219 mi
Registration #4	2022-04-11	19.292 mi
Registration #5	2022-04-11	19.292 mi
Registration #6		71.777 es
Registration #7		11.777 es
Registration #8		71.777 es
Registration #9		11.177 es
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Safety ratings

NCAP rating	★★★ ★★
Adult	61%
Children	74%
Pedestrian	68%
Safety systems	38%
Overall rating	60%
Video	see crash video



Dimensions & weight

Width	1600 mm
Height	1540 mm
Length	3600 mm
Wheel base	2425 mm
Kerb weight	885 kg
Max. allowed weight	1260 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	K10BS1079983

CarCheck.co.uk page 11/11