



General information

Make	FORD
Model	FOCUS ST-3
Colour	White
Year of manufacture	2010
Top speed	150 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	223 BHP
Max. torque	320 Nm at 4.000 rpm
Engine capacity	2.521 cc
Cylinders	5
Fuel type	Petrol
Consumption city	20.5 mpg
Consumption extra urban	41.5 mpg
Consumption combined	30.4 mpg
CO2 emission	224 g/km
CO2 label	K





Internet history

Entry 3

Date 2023-12-14

Pictures 8




source: g3remarketing.co.uk

Entry 2

Date 2022-03-22

Pictures 13

Listing price [View report](#)



source: cargurus.co.uk

Entry 1

Date 2021-01-30

Pictures 10

Listing price [View report](#)



source: autoonline.co.uk



MOT history

MOT expiry date	2024-05-24
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	68
Total items failed	2

MOT #15	2023-05-25 07:58
MOT test number	357017423415
Result	✓ Passed
Next expiry date	2024-05-24

MOT #14	2023-05-19 13:49
MOT test number	866088436300
Result	✗ Failed
MAJOR Horn not working (7.7 (a))	

MOT #13	2022-03-31 14:59
MOT test number	485731103657
Result	✓ Passed

MOT #12	2020-11-02 17:23
MOT test number	456792163614
Result	✓ Passed

**MOT #11**

2019-06-28 08:49

MOT test number

239422645483

Result

✓ Passed

Advice Central Front Undertray not fully secure missing (8.1.1 (b) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #10**

2019-06-26 10:00

MOT test number

917175722405

Result

✗ Failed

Advice Central Front Undertray not fully secure missing (8.1.1 (b) (i))**MAJOR** Offside Front Headlamp insecure (4.1.1 (c))**DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Central Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge on limit e.r.a. (5.2.3 (e))**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))



MOT #9	2018-06-29 10:29
MOT test number	135777480088
Result	✓ Passed
Advice	Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #8	2018-06-22 14:48
MOT test number	635493321417
Result	✗ Failed
MAJOR	Power steering malfunctioning (2.1.5 (a))
Advice	Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Both rear brake hose ferrules corroded



MOT #7	2018-06-05 11:37
MOT test number	262544859520
Result	✗ Failed

DANGEROUS Offside Upper Engine mounting fractured (6.1.8 (a) (ii))

MAJOR Nearside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))

Advice Both rear directional indicators slightly discolored

MAJOR Nearside Headlamp aim too low (4.1.2 (a))

MAJOR Offside Front Power steering pipe/hose excessively damaged fouling on bottom / crank pulley (2.1.5 (g) (i))

Advice Offside Rear tyre worn on edges

MAJOR Offside Headlamp not working on main beam (4.1.1 (a) (ii))

Minor Nearside Rear Tyre obviously under inflated (5.2.3 (h) (i))

Advice Nearside Rear tyre worn on inner edge

MAJOR Offside Front Position lamp not working (4.2.1 (a))

MAJOR Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

DANGEROUS Windscreen in such a condition that visibility through swept area is seriously affected (3.2 (c) (ii))

MAJOR Nearside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))

Advice Both front fog lights inoperative

MAJOR Offside Rear fog lamp not working (4.5.1 (a) (ii))

DANGEROUS Nearside Rear Road wheel fractured inner rim (5.2.2 (a))

Advice Power steering pump has slight seepage (2.1.5 (a))

Advice Coolant level low

MAJOR Offside Headlamp aim too low (4.1.2 (a))

MAJOR Central Rear Seat belt retracting mechanism defective (7.1.2 (e))

Advice Both rear brake hose ferrules corroded

MAJOR Nearside Front Position lamp not working (4.2.1 (a))

MAJOR Reversing lamp switch does not operate automatically when reverse gear is selected both reverse lights inoperative (4.6.3 (a))

Advice Battery loose

Advice Offside Front Nail in tyre

MAJOR Windscreen washer not working both front (3.5 (a))

**MOT #6** 2017-01-11 17:00**MOT test number** 856822591930**Result** ✓ Passed

- Advice** Front Inner Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice** Offside Play in steering rack inner joint(s)

MOT #5 2016-12-30 11:41**MOT test number** 987681681581**Result** ✗ Failed

- Advice** Front Inner Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)
- Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Nearside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice** Offside Play in steering rack inner joint(s)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2015-12-14 14:22**MOT test number** 746526280912**Result** ✓ Passed

- Advice** Advise surface corrosion to brake discs
- Advice** Advise slight play in rear suspension arm mounts
- Advice** Advise uneven tyre wear on rear tyres

**MOT #3** 2014-12-22 12:36**MOT test number** 788176554339**Result** ✓ Passed**Notice** Front tyre treads wearing low on inner edges**MOT #2** 2014-01-04 16:21**MOT test number** 807704504076**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #1** 2013-05-07 10:51**MOT test number** 896117123183**Result** ✓ Passed**Notice** Nail in offside rear tyre**Notice** Under-trays fitted obscuring some underside components**Notice** Child seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
24 May 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	24 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-05-13
Last registration	2023-05-25
Complete history	See info



Registration #1	2010-05-13	11 mi
Registration #2	2013-05-07	22.449 mi
Registration #3	2014-01-04	25.433 mi
Registration #4	2014-12-22	33.553 mi
Registration #5	2015-12-14	39.410 mi
Registration #6	2016-12-30	51.763 mi
Registration #7	2017-01-11	51.919 mi
Registration #8	2018-06-05	53.810 mi
Registration #9	2018-06-22	53.820 mi
Registration #10	2019-05-29	55.377 mi
Registration #11	2019-05-29	55.377 mi
Registration #12	2019-05-29	55.377 mi
Registration #13	2019-05-29	55.377 mi
Registration #14	2019-05-29	55.377 mi
Registration #15	2019-05-29	55.377 mi
Registration #16	2019-05-29	55.377 mi
Registration #17	2019-05-29	55.377 mi
Registration #18	2019-05-29	55.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1839 mm
Height	1497 mm
Length	4357 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1890 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4

Number of axles	2
Engine number	AU03984