



report date: 2024-03-28

General information

Make	VAUXHALL
Model	AGILA CLUB
Colour	Black
Year of manufacture	2008
Top speed	109 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	114 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	131 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-05-08
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-22
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	38
Total items failed	8

MOT #17	2023-06-16 16:30
MOT test number	610264069141
Result	✓ Passed
Next expiry date	2024-06-22
Advice	Rear Brake pipe corroded, covered in grease or other material On rear beam (1.1.11 (c))

MOT #16	2022-06-23 15:05
MOT test number	275242370541
Result	✓ Passed

MOT #15	2022-06-22 10:10
MOT test number	465083003377
Result	✗ Failed
Fail	Nearside Front Inner Brake disc in such a condition that it is seriously weakened face corroded (1.1.14 (a) (ii))
Fail	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
Fail	Offside Front Inner Brake disc in such a condition that it is seriously weakened face corroded (1.1.14 (a) (ii))
Fail	Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #14**

2021-11-29 12:39

MOT test number

255426043582

Result

✓ Passed

- Minor** Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Clutch operation heavy
- Advice** Front Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Underside of gearbox oily
- Advice** Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement Both (5.3.4 (a) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))
- Advice** Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

MOT #13

2021-11-29 09:36

MOT test number

121086534747

Result

✗ Failed

- Advice** Clutch operation heavy
- Advice** Front Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))
- Advice** Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Underside of gearbox oily
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Minor** Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))
- Advice** Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement Both (5.3.4 (a) (i))

**MOT #12**

2020-12-02 11:15

MOT test number

612357891260

Result

✓ Passed

- Advice** Nearside front wheel inner rim slightly damaged
- Advice** Offside Front Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))
- Advice** Gearbox oily
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Clutch heavy in operation
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))

MOT #11

2020-12-01 17:03

MOT test number

122638969778

Result

✗ Failed

- Advice** Nearside front wheel inner rim slightly damaged
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))
- Advice** Gearbox oily
- Fail** Nearside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))

**MOT #10** 2019-06-24 11:11**MOT test number** 361123321901**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge and perished (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge and perished (5.2.3 (e))**MOT #9** 2018-06-28 13:20**MOT test number** 481441678339**Result** ✓ Passed**MOT #8** 2018-06-27 11:17**MOT test number** 908796761704**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Offside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #7** 2017-10-23 07:42**MOT test number** 196953081660**Result** ✓ Passed**MOT #6** 2016-10-26 07:42**MOT test number** 517602063619**Result** ✓ Passed**Advice** Wear on outer edge of tread on nearside front Tyre



MOT #5	2015-10-26 08:51
---------------	------------------

MOT test number	364056177126
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2014-10-27 09:22
---------------	------------------

MOT test number	455840204305
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	Oil leak
---------------	----------

MOT #3	2013-10-28 08:38
---------------	------------------

MOT test number	299401803354
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	---

MOT #2	2012-10-22 08:56
---------------	------------------

MOT test number	335596292488
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	Wear on outer edge of nearside front Tyre
---------------	---

MOT #1	2011-10-18 08:52
---------------	------------------

MOT test number	588391491248
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
22 June 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	22 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	GY58WRT
Plate since	2019-06-29
Current registration	GY58WRT
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-10-31
Last registration	2023-06-16
Complete history	See info



Registration #1	2008-10-31	17 mi
Registration #2	2011-10-18	10.431 mi
Registration #3	2012-10-22	15.023 mi
Registration #4	2013-10-28	20.808 mi
Registration #5	2014-10-27	25.818 mi
Registration #6	2015-10-26	31.769 mi
Registration #7	2016-10-26	38.675 mi
Registration #8	2017-10-23	47.133 mi
Registration #9	2018-06-27	49.192 mi
Registration #10	2018-06-28	49.193 mi
Registration #11	2019-06-27	55.277 mi
Registration #12	2019-06-27	55.277 mi
Registration #13	2019-06-27	55.277 mi
Registration #14	2019-06-27	55.277 mi
Registration #15	2019-06-27	55.277 mi
Registration #16	2019-06-27	55.277 mi
Registration #17	2019-06-27	55.277 mi
Registration #18	2019-06-27	55.277 mi
Registration #19	2019-06-27	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	990 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1078130