





General information

Make	MAZDA
Model	2 SE
Colour	Red
Year of manufacture	2014
Top speed	104 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP	0 < 101 A
Max. torque	119 Nm at 3.500 rpm	101 - 120
Engine capacity	1.349 сс	121 - 140
Cylinders	4	141 - 165
Fuel type	Petrol	166 - 185
Consumption city	45.6 mpg	186 - 225
Consumption extra urban	65.7 mpg	225+
Consumption combined	56.5 mpg	
CO2 emission	115 g/km	
CO2 label	С	





Internet history

Entry 1

Date Pictures 2021-05-24

25

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-18
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	4
Total items failed	9

MOT #12	2023-04-27 11:27
MOT test number	766624041523
Result	✓ Passed
Next expiry date	2024-05-18

MOT #11	2022-04-29 13:51
MOT test number	317452747396
Result	✓ Passed

MOT #10	2022-04-29 11:24
MOT test number	756086611314
Result	× Failed
 Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Fail Offside Track rod end ball joint has excessive play (2.1.3 (b) (i)) 	

МОТ #9	2021-05-19 16:32
MOT test number	590979901058
Result	✓ Passed
MOT #8	2020-04-08 08:38

MOT test number	921582047499
Result	✓ Passed





MOT #7	2020-04-08 08:38
MOT test number	248163675703
Result	× Failed
Pass with rectification (ii))	Front Windscreen wiper does not clear the windscreen effectively Both (3.4 (b)
Pass with rectification (h))	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3

MOT #6	2019-04-25 11:13
MOT test number	421563186196
Result	✓ Passed

MOT #5	2019-04-23 16:31
MOT test number	410387161346
Result	🗙 Failed
Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Fail Windscreen washer provides insufficient washer liquid (3.5 (a))	
Fail Driver's view of an obligatory external mirror materially affected by an obstruction air freshers and toy hanging from mirror (3.1 (a) (ii))	

МОТ #4	2019-04-09 11:06	
MOT test number	876120675325	
Result	🗙 Failed	
Fail Front Brakes imbalanced across an axle Axle 1 (1.2.1 (b) (i))		
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Minor Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))	
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened	ed (1.1.14 (a) (ii))	

MOT #3	2018-04-06 16:30
MOT test number	307930306483
Result	✓ Passed





MOT #2	2018-04-06 07:17
MOT test number	681559000071
Result	🗙 Failed
Fail Windscreen wiper does not clear the windscreen effectively (8.2.2)	
MOT #1	2017-09-01 14:24
MOT test number	438129329308
Result	✓ Passed
Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)	





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	AMPLI
Date	1. the second se
Category	ante
Туре	

Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	
No. of the second se	
Plate sitcs	
Funte since Current registration	
Plate since Falle since	1000-20-20





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-09-01
Last registration	2023-04-27
Complete history	See info



Registration #1	2014-09-01	19 mi
Registration #2	2017-09-01	37.601 mi
Registration #3	2018-04-06	43.409 mi
Registration #4	2018-04-06	43.409 mi
Registration #5	2019-04-09	69.438 mi
Registration #6	2019-04-23	69.350 mi
Registration #7	2019-04-25	69.355 mi
Registration #8		11.317 est
Registration #8 Registration #9		11.577 es
-		01.000 est 01.000 est 01.000 est
Registration #9		01.000 est 01.000 est 01.000 est 01.000 est
Registration #9 Registration #10		0.000 es
Registration #9 Registration #10 Registration #11		0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es



Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1695 mm
Height	1475 mm
Length	3885 mm
Wheel base	2490 mm
Kerb weight	1030 kg
Max. allowed weight	1485 kg
Additional information	
Additional information Fuel tank capacity	42 I
	42 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 5