





report date: 2024-03-28

## General information

Make	BMW
Model	X6 XDRIVE30D M SPORT
Colour	White
Year of manufacture	2013
Top speed	138 mph
0 - 60 mph	7.6 seconds
Gearbox	8 speed automatic

## Engine & fuel consumption

Power	241 BHP
Max. torque	540 Nm at 1.750 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	42.2 mpg
Consumption combined	38.2 mpg
CO2 emission	195 g/km
CO2 label	J



CarCheck.co.uk page 1/12



report date: 2024-03-28

## Internet history

#### Entry 1

Date	2021-10-04	
Pictures	1	
Listing price	<u>View report</u>	



source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

## MOT history

MOT expiry date	2025-01-03
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	12
Total items failed	4

MOT #11		2024-01-03 10:37
MOT test	number	223628910193
Result		✓ Passed
Next expi	ry date	2025-01-03
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

2023-01-03 12:15
539303919323
✓ Passed

MOT #9		2022-12-20 15:45
MOT test no	umber	547634239102
Result		<b>×</b> Failed
Fail Offs	side Rear Coil spring fractured or broken (5.3.1 (b) (i))	
<b>Fail</b> From	nt Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #8	2022-01-04 13:17
MOT test number	108491963630
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

**MOT #7** 2021-07-15 14:56

**MOT test number** 932187260532

**Result** 
✓ Passed

MOT #6 2020-10-15 08:37

**MOT test number** 796800810797

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2020-10-09 09:43

**MOT test number** 579160121901

Result X Failed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Rear Parking brake inoperative on one side hand brake not working (1.4.1 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #4 2019-04-11 08:48

**MOT test number** 389643870620

Advice Offside Rear Tyre worn close to legal limit/worn on edge wearing on inside edges (5.2.3 (e))

MOT #3 2018-04-07 09:08

**MOT test number** 221900165765

**Result** ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #2		2017-03-31 10:31
MOT test	number	331121486609
Result		✓ Passed
Advice	Nearside Rear Nail in tyre	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #1	2016-04-02 08:20
MOT test number	623221564919
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	3 January 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Venicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

## Owner history

For how long did the current and previous owner(s) have this BMW? How many owners of Check it in the premium report and see all owner registrations. Download the full report		ve?
manus .		
***************************************		
********		
***************************************		
	More info	>
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	NK NIZ	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-28

### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



SG13SFK report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-04-12
Last registration	2024-01-03
Complete history	See info



Registration #1	2013-04-12	20 mi
Registration #2	2016-04-02	42.537 mi
Registration #3	2017-03-31	47.730 mi
Registration #4	2018-04-07	52.057 mi
Registration #5	2019-04-11	56.734 mi
Registration #6	2020-10-09	64.330 mi
Registration #7	2020-10-15	642.074 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		10,777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1933 mm
Height	1776 mm
Length	4857 mm
Wheel base	2933 mm
Kerb weight	2075 kg
Max. allowed weight	2965 kg

# Additional information

Fuel tank capacity	85 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/12

Number of axles 2
Engine number 31158378