



report date: 2024-03-28

General information

Make	LEXUS
Model	IS 300H EXECUTIVE EDITION
Colour	Red
Year of manufacture	2016
Top speed	125 mph
0 - 60 mph	8.1 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	220 BHP
Max. torque	221 Nm at 4.200 rpm
Engine capacity	2.494 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	61.4 mpg
Consumption extra urban	61.4 mpg
Consumption combined	64.2 mpg
CO2 emission	101 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-06-07
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-11
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	16
Total items failed	0

MOT #6	2023-12-12 15:20
MOT test number	453574528009
Result	✓ Passed
Next expiry date	2024-12-11
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened front discs lipped (1.1.14 (a) (ii))
Advice	Front Brake pad(s) wearing thin front pads 80% worn (1.1.13 (a) (ii))

MOT #5	2022-12-12 16:15
MOT test number	914240970538
Result	✓ Passed
Advice	Engine covers and under trays fitted

**MOT #4**

2022-12-09 14:49

MOT test number

271749153681

Result**✗ Failed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge on legal limit (5.2.3 (e))**DANGEROUS** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Engine covers and under trays fitted**Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing smooth on edge(s) (5.2.3 (e))**MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on legal limit (5.2.3 (e))**Advice** Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))**Advice** Front wipers streaking / smearing**DANGEROUS** Offside Rear Tyre has ply or cords damaged (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge wearing smooth on edge(s) (5.2.3 (e))**MOT #3**

2021-12-03 16:37

MOT test number

102795245966

Result**✓ Passed****MOT #2**

2020-11-12 14:14

MOT test number

206653841320

Result**✓ Passed****Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



MOT #1	2019-11-07 09:37
MOT test number	268791293555
Result	✓ Passed
Advice	Front tyres worn inner edges
Advice	Front tyres perished



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
11 December 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	11 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	B
Single payment (12 months)	£ 10,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 10,50,-



Damage history

Check the damage history for this LEXUS. See if, where and when this LEXUS had damage and the car repair costs. We also check if this LEXUS was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra LEXUS salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LEXUS in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LEXUS? How many owners did this LEXUS have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this LEXUS had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this LEXUS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LEXUS has been settled.

If not, and you buy this LEXUS then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LEXUS is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-11-23
Last registration	2023-12-12
Complete history	See info



Registration #1	2016-11-23	20 mi
Registration #2	2019-11-07	35.549 mi
Registration #3	2020-11-12	42.083 mi
Registration #4	2021-11-12	42.083 mi
Registration #5	2022-11-12	42.083 mi
Registration #6	2023-11-12	42.083 mi
Registration #7	2023-11-12	42.083 mi
Registration #8	2023-12-12	42.083 mi

More info >



Car features

The LEXUS factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete LEXUS factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	85%
Pedestrian	80%
Safety systems	66%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1430 mm
Length	4665 mm
Wheel base	2800 mm
Kerb weight	1720 kg
Max. allowed weight	2145 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	2AR1338001