



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 ZEST 3
Colour	Silver
Year of manufacture	-
Top speed	98 mph
0 - 60 mph	15.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	60 BHP
Max. torque	94 Nm at 2.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	34.4 mpg
Consumption extra urban	56.5 mpg
Consumption combined	45.6 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-03
Pictures	9
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #20	2023-05-10 13:45
MOT test number	407283620707
Result	✓ Passed
Next expiry date	2024-05-09

MOT #19	2021-02-16 11:44
MOT test number	979971895220
Result	✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Exhaust has a minor leak of exhaust gases Back box (6.1.2 (a))

MOT #18	2020-02-17 12:37
MOT test number	472342446501
Result	✓ Passed

Advice Offside Play in steering rack inner joint(s)

Advice Hub caps fitted wheel bolts not checked

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #17** 2020-02-05 11:38**MOT test number** 400339995776**Result** ✗ Failed**MAJOR** Offside Front Service brake excessively fluctuating (1.2.1 (e))**Advice** Hub caps fitted wheel bolts not checked**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))**MAJOR** Nearside Front Service brake excessively fluctuating (1.2.1 (e))**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Offside Play in steering rack inner joint(s)**MAJOR** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #16** 2019-03-07 11:54**MOT test number** 907982951073**Result** ✓ Passed**Advice** Oil leak, but not excessive Gear box (8.4.1 (a) (i))**MOT #15** 2018-02-28 09:59**MOT test number** 885788984373**Result** ✓ Passed**MOT #14** 2017-03-09 08:43**MOT test number** 671343342038**Result** ✓ Passed**MOT #13** 2016-03-10 14:24**MOT test number** 180701931163**Result** ✓ Passed

**MOT #12** 2016-03-10 09:24**MOT test number** 243774769197**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Rear Exhaust system not adequately supported (7.1.1)**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #11** 2015-03-12 14:55**MOT test number** 439591475087**Result** ✓ Passed**MOT #10** 2015-03-12 08:53**MOT test number** 206311075072**Result** ✗ Failed**Fail** Offside Rear Shock absorber has an excessively worn bush (2.7.4)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #9** 2014-03-11 10:04**MOT test number** 949360874062**Result** ✓ Passed**MOT #8** 2014-03-11 10:04**MOT test number** 338940674013**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #7** 2013-03-14 10:03**MOT test number** 137333973074**Result** ✓ Passed

**MOT #6** 2012-03-15 10:41**MOT test number** 109895672041**Result** ✓ Passed**MOT #5** 2011-03-08 09:56**MOT test number** 386147961041**Result** ✓ Passed**Notice** Radiator Leaking**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2010-03-03 11:53**MOT test number** 782112960024**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #3** 2010-03-03 10:43**MOT test number** 781732860082**Result** ✗ Failed**Fail** Rear registration plate character(s) not correctly formed (6.3.4b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Fail** Front registration plate character(s) not correctly formed (6.3.4b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #2** 2009-03-18 14:41**MOT test number** 211307679040**Result** ✓ Passed**MOT #1** 2008-03-12 14:34**MOT test number** 582862578001**Result** ✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-03-22
Last registration	2023-05-10
Complete history	See info



Registration #1	2005-03-22	29 mi
Registration #2	2008-03-12	18.016 mi
Registration #3	2009-03-18	24.653 mi
Registration #4	2010-03-03	31.997 mi
Registration #5	2010-03-03	31.997 mi
Registration #6	2011-03-08	40.165 mi
Registration #7	2012-03-15	46.453 mi
Registration #8	2013-03-14	51.937 mi
Registration #9	2014-03-11	56.513 mi
Registration #10	2015-03-12	61.648 mi
Registration #11	2015-03-12	61.648 mi
Registration #12	2016-03-12	66.783 mi
Registration #13	2017-03-12	71.918 mi
Registration #14	2018-03-12	77.053 mi
Registration #15	2019-03-12	82.188 mi
Registration #16	2020-03-12	87.323 mi
Registration #17	2021-03-12	92.458 mi
Registration #18	2022-03-12	97.593 mi
Registration #19	2023-03-12	102.728 mi
Registration #20	2024-03-12	107.863 mi
Registration #21	2025-03-12	112.998 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	985 kg
Max. allowed weight	1405 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number

FP7N4789506