



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 SE
Colour	Blue
Year of manufacture	2007
Top speed	130 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	38.7 mpg
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-07-13
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-10-12
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	24
Total items failed	8

MOT #16	2023-10-12 11:39
MOT test number	469874097020
Result	✓ Passed
Next expiry date	2024-10-12

MOT #15	2023-10-10 10:58
MOT test number	139748861760
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #14	2022-10-13 15:20
MOT test number	542861622972
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13**

2022-10-12 07:54

MOT test number

616736933680

Result**✗ Failed****Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12**

2021-10-08 10:18

MOT test number

551290369279

Result**✓ Passed****MOT #11**

2020-10-02 08:28

MOT test number

420377467301

Result**✓ Passed****MOT #10**

2020-09-29 16:00

MOT test number

577932473854

Result**✗ Failed****Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #9** 2019-04-01 09:32**MOT test number** 788648291892**Result** ✓ Passed

- Advice** Offside Front Tyre slightly damaged/cracking or perishing side wall (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge edges (5.2.3 (e))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing side wall (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge edges (5.2.3 (e))
- Advice** Offside Front Nail in tyre

MOT #8 2018-03-29 16:19**MOT test number** 955948555063**Result** ✓ Passed

- Advice** Nearside Front deep cut in sidewall but cords not exposed.

MOT #7 2016-02-05 15:50**MOT test number** 176429331840**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2014-09-25 09:34**MOT test number** 638758464250**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Both rear tyres slight stepping on outer edges

**MOT #5** 2014-09-25 09:34**MOT test number** 325938464235**Result** ✗ Failed**Notice** Both rear tyres slight stepping on outer edges**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2013-09-07 09:16**MOT test number** 325960153406**Result** ✓ Passed**MOT #3** 2012-09-20 09:20**MOT test number** 866274362246**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2011-09-25 15:38**MOT test number** 657308661224**Result** ✓ Passed**MOT #1** 2010-09-16 16:34**MOT test number** 964749850242**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
12 October 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	12 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 
Plate since	2019-09-29
Current registration	 
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-09-07
Last registration	2023-10-12
Complete history	See info



Registration #1	2007-09-07	14 mi
Registration #2	2010-09-16	12.786 mi
Registration #3	2011-09-25	16.716 mi
Registration #4	2012-09-20	20.211 mi
Registration #5	2013-09-07	27.122 mi
Registration #6	2014-09-25	34.504 mi
Registration #7	2016-02-05	37.657 mi
Registration #8	2018-03-29	40.960 mi
Registration #9	2019-04-01	49.086 mi
Registration #10	2020-04-01	55.377 mi
Registration #11	2021-04-01	55.377 mi
Registration #12	2022-04-01	55.377 mi
Registration #13	2023-04-01	55.377 mi
Registration #14	2024-04-01	55.377 mi
Registration #15	2025-04-01	55.377 mi
Registration #16	2026-04-01	55.377 mi
Registration #17	2027-04-01	55.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1328 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	73027