



report date: 2024-09-18

General information

Make	MINI
Model	CLUBVAN ONE
Colour	Black
Year of manufacture	2013
Top speed	115 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	97 BHP
Max. torque	153 Nm at 3.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	129 g/km
CO2 label	D






## Internet history

### Entry 1

Date	2021-07-03
Pictures	9
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-06-05
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	18
Total items failed	5

**MOT #11** 2024-05-23 10:22

**MOT test number** 744928612566

**Result** ✓ Passed

**Next expiry date** 2025-06-05

**Advice** Offside Front Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #10** 2023-05-11 14:55

**MOT test number** 464700374630

**Result** ✓ Passed

**MOT #9** 2023-05-11 08:46

**MOT test number** 527259483335

**Result** ✗ Failed

**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2022-06-06 13:59

**MOT test number** 968730858084

**Result** ✓ Passed

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))



<b>MOT #7</b>	2021-06-03 09:30
<b>MOT test number</b>	410073873313
<b>Result</b>	✓ Passed

<b>MOT #6</b>	2020-08-12 12:57
<b>MOT test number</b>	470522247313
<b>Result</b>	✓ Passed

- Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Tyre worn close to legal limit/worn on edge all worn on inner edges (5.2.3 (e))
- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Outer Tyre slightly damaged/cracking or perishing sidewall cracking (5.2.3 (d) (ii))

<b>MOT #5</b>	2019-08-16 08:08
<b>MOT test number</b>	164712074798
<b>Result</b>	✓ Passed

- Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

<b>MOT #4</b>	2019-08-16 08:08
<b>MOT test number</b>	310117509326
<b>Result</b>	✗ Failed

- Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Pass with rectification** Nearside Side repeater not working (4.4.1 (a) (ii))
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))



<b>MOT #3</b>	2018-07-17 14:17
<b>MOT test number</b>	467036597072
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))

<b>MOT #2</b>	2017-06-16 14:32
<b>MOT test number</b>	341094184350
<b>Result</b>	✓ Passed
<b>Advice</b>	Windscreen has damage to an area less than a 10mm circle within zone 'A' chips (8.3.1a)
<b>Advice</b>	Oil leak around sump/sump plug

<b>MOT #1</b>	2017-06-15 15:51
<b>MOT test number</b>	307889752227
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Offside Headlamp aim too low (1.8)
<b>Fail</b>	Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)
<b>Pass with rectification</b>	Nearside Headlamp aim too low (1.8)
<b>Advice</b>	Oil leak around sump/sump plug
<b>Advice</b>	Windscreen has damage to an area less than a 10mm circle within zone 'A' chips (8.3.1a)



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 June 2025

✓  
**MOT**

**Expires:**  
5 June 2025

**Tax status** Valid until 1 June

**Days left** 239

**MOT expiry date** 5 June 2025

**Full MOT history** [See MOT history](#)

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-




Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	<b>GN63YLL</b>
Plate since	2019-09-18
Current registration	<b>GN63YLL</b>
Plate since	2019-09-18

More info >



**Finance check**

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-09-09
Last registration	2024-05-23
Complete history	<a href="#">See info</a>



Registration #1	2013-09-09	29 mi
Registration #2	2017-06-15	82.148 mi
Registration #3	2017-06-16	82.149 mi
Registration #4	2018-07-17	88.196 mi
Registration #5	2019-08-16	91.761 mi
Registration #6	2019-08-16	91.761 mi
Registration #7	2020-08-12	93.410 mi
Registration #8	2021-05-20	95.277 mi
Registration #9	2022-05-20	95.277 mi
Registration #10	2023-05-20	95.277 mi
Registration #11	2024-05-20	95.277 mi
Registration #12	2024-05-20	95.277 mi
Registration #13	2024-05-23	95.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1683 mm
Height	1426 mm
Length	3961 mm
Wheel base	2547 mm
Kerb weight	1140 kg
Max. allowed weight	1640 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of seats	2
Number of axles	2
Engine number	A368J549