





report date: 2024-03-28

General information

Make	PEUGEOT
Model	BOXER BLUE HDI 335 L2H2 PROFESSIONAL P/V
Colour	Silver
Year of manufacture	2018
Top speed	92 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	45.6 mpg
CO2 emission	163 g/km
CO2 label	G



CarCheck.co.uk page 1/11



Internet history

E	n	tr	у	1

Date	2021-07-06
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-01-17
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	9
Total items failed	9

MOT #6	2024-01-18 13:42
MOT test number	493605907410
Result	✓ Passed
Next expiry date	2025-01-17

MOT #5	2024-01-18 08:43
MOT test number	568458240206
Result	🗙 Failed
Fail Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))	
Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))	
Advice Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))	
Fail Front Windscreen washer provides insufficient washer liquid both (3.5 (a))	
Fail Parking brake inoperative on one side both sides (1.4.1 (a))	
Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #4

MOT test number

604635290353

Result

Advice Offside Rear tyre perished

Advice Nearside Rear Nail in tyre

 MOT #3
 2021-08-13 09:08

 MOT test number
 556491389987

 Result
 ✓ Passed

 MOT #2
 2021-05-25 09:15

 MOT test number
 626784853261

 Result
 ✓ Passed

MOT #1 2021-05-12 14:33

MOT test number 579971935771

Result X Failed

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Nearside Front Side repeater lens defective such that the emitted light is adversely affected mirror lense (4.4.1 (b) (ii))

Advice Offside mirror cover broken

Advice Offside Front blind spot mirror damaged

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Power steering pipe insecure

Fail Offside Front Side repeater lens defective such that the emitted light is adversely affected mirror lense (4.4.1 (b) (ii))

Advice Nearside Rear lamp unit damaged

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	17 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

factor scincore

NA18PWJ

report date: 2024-03-28

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate Changes See in this check if this PEUGEOT had different number plates.

See in this check if this PEUGEOT had different number plates.

More info >

CarCheck.co.uk page 8/11



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-06-06
Last registration	2024-01-18
Complete history	See info



Registration #1	2018-06-06	14 mi
Registration #2	2021-05-12	51.185 mi
Registration #3	2021-05-25	51.185 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

page 10/11 CarCheck.co.uk



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
S0567	
50569	

Safety ratings

NCAP rating	***
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



Dimensions & weight

Width	2050 mm
Height	2522 mm
Length	5413 mm
Wheel base	3450 mm
Kerb weight	1925 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	90 I	
Fuel delivery	Direct Injection	
Number of seats	3	
Number of axles CarCheck.co.uk	2 page 11	/11