



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | VAUXHALL |
| Model | MERIVA SE |
| Colour | Brown |
| Year of manufacture | 2016 |
| Top speed | 117 mph |
| 0 - 60 mph | 11.3 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 118 BHP |
| Max. torque | 175 Nm at 1.750 rpm |
| Engine capacity | 1.364 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 36.2 mpg |
| Consumption extra urban | 58.9 mpg |
| Consumption combined | 47.9 mpg |
| CO2 emission | 139 g/km |
| CO2 label | E |





Internet history

Entry 3


| | |
|---------------|-----------------------------|
| Date | 2022-12-02 |
| Pictures | 10 |
| Listing price | View report |



source: cargurus.co.uk

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2022-03-18 |
| Pictures | 12 |
| Listing price | View report |



source: cargurus.co.uk

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-05-27 |
| Pictures | 0 |
| Listing price | View report |

source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-02-12 |
| MOT pass rate | 88 % |
| MOT passed | 7 |
| Failed MOT tests | 1 |
| Total advice items | 3 |
| Total items failed | 1 |

| | |
|------------------|------------------|
| MOT #8 | 2024-02-08 09:18 |
| MOT test number | 995090911032 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-12 |

| | |
|-----------------|------------------|
| MOT #7 | 2023-02-13 11:52 |
| MOT test number | 517146363462 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #6 | 2022-04-11 13:02 |
| MOT test number | 850584396714 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #5 | 2021-07-21 07:59 |
| MOT test number | 264805921713 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #4 | 2021-07-19 09:17 |
| MOT test number | 739068791570 |
| Result | ✗ Failed |

Minor Offside Headlamp lens slightly defective Condensation in lamp (4.1.1 (b) (i))

Fail Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #3** 2021-01-15 09:19**MOT test number** 366808763951**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2020-01-13 09:27**MOT test number** 369212810042**Result** ✓ Passed**Advice** Wear on outer edge of tread on Nearside Front Tyre**MOT #1** 2019-01-24 11:59**MOT test number** 556963203933**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
12 February 2025

| | |
|------------------|---------------------------------|
| Tax status | Valid until 1 July |
| Days left | 63 |
| MOT expiry date | 12 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 48 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | BX16HDN |
| Plate since | 2019-06-29 |
| Current registration | BX16HDN |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 12 |
| First mileage registration | 2016-03-01 |
| Last registration | 2024-02-08 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2016-03-01 | 20 mi |
| Registration #2 | 2019-01-24 | 12.696 mi |
| Registration #3 | 2020-01-13 | 24.839 mi |
| Registration #4 | 2021-01-15 | 35.756 mi |
| Registration #5 | 2021-07-19 | 39.402 mi |
| Registration #6 | | |
| Registration #7 | | |
| Registration #8 | | |
| Registration #9 | | |
| Registration #10 | | |
| Registration #11 | | |
| Registration #12 | | |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 89% |
| Children | 77% |
| Pedestrian | 55% |
| Safety systems | 86% |
| Overall rating | 80% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1994 mm |
| Height | 1615 mm |
| Length | 4300 mm |
| Wheel base | 2644 mm |
| Kerb weight | 1408 kg |
| Max. allowed weight | 1930 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 54 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | B14NEL -19NC4177LUH |