





report date: 2024-03-28

General information

| Make | CITROEN |
|---------------------|---------------------------------------|
| Model | DISPATCH 1000 L1H1 ENTERPRISE P/V HDI |
| Colour | Black |
| Year of manufacture | 2015 |
| Top speed | 90 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 89 BHP |
|-------------------------|---------------------|
| Max. torque | 180 Nm at 1.500 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 35.8 mpg |
| Consumption extra urban | 45.6 mpg |
| Consumption combined | 42.2 mpg |
| CO2 emission | 177 g/km |
| CO2 label | I |



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-06-26

Pictures 25

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



| B 4 | \sim $-$ | | |
|-------|-------------|------|--------|
| 10.71 | $^{\prime}$ | hic | tory |
| 101 | C I | 1115 | I OI V |
| | • | | , |

| MOT expiry date | 2024-06-07 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 6 |
| Failed MOT tests | 2 |
| Total advice items | 22 |
| Total items failed | 0 |

| MOT #8 | 2023-06-08 10:49 |
|------------------|------------------|
| MOT test number | 127173602025 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-07 |

| MOT #7 | 2023-06-06 14:20 |
|--|------------------------------|
| MOT test number | 988701530498 |
| Result | X Failed |
| Minor Offside Rear Registration plate lamp inoperative in the case of mult (4.7.1 (b) (i)) | tiple lamps or light sources |
| MAJOR Offside Front Position lamp not working (4.2.1 (a) (ii)) | |
| DANGEROUS Offside Front Wheel bearing play so excessive it is likely to | break up (5.1.3 (a) (ii)) |
| MAJOR Offside Obligatory mirror does not provide a view to the rear (3.3 | (c)) |

| MOT #6 | 2022-04-22 14:54 |
|--|---|
| MOT test | number 418283883094 |
| Result | ✓ Passed |
| Advice | Central Rear Upper hi - level brake lamp in-operative |
| Advice Nearside Front Outer Road wheel slightly distorted slightly distorted on outer bead (5.2.2 (c) (i)) | |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |

CarCheck.co.uk page 3/12



LK65ZGJ

report date: 2024-03-28

MOT #5 2022-04-21 11:09

MOT test number 501821436132

Result X Failed

MAJOR Front Power steering component leaking (2.1.5 (a))

Advice Nearside Front Outer Road wheel slightly distorted slightly distorted on outer bead (5.2.2 (c) (i))

DANGEROUS Front Hydraulic fluid leaking continuously posing a serious risk to road safety power steering rack leaking (8.4.1 (a) (ii))

Advice Vehicles internal headlight adjuster altered to recheck lights

MAJOR Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Offside Front Nail in tyre nail in tread

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MAJOR Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords tyre cut to cords on inner edge (5.2.3 (d) (i))

Advice Central Rear Upper hi - level brake lamp in-operative

Advice Offside Front Upper Items removed from driver's view prior to test remove phone holder from

view on windscreen

MAJOR Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #4 2021-05-15 12:16

MOT test number 897008071758

Result ✓ Passed

MOT #3 2020-05-21 08:31

MOT test number 102715887832

Result
✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/12



MOT #2

MOT test number

738754523866

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

| MOT #1 | 2018-04-27 10:02 |
|-----------------|------------------|
| MOT test number | 387999515053 |
| Result | ✓ Passed |

CarCheck.co.uk page 5/12



Tax & MOT check



| Tax status | Valid until 1 January |
|------------------|-----------------------|
| Days left | 246 |
| MOT expiry date | 7 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 39 |
|---------------------------|------------|
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months) | £ 151,25,- |

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

| For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full in | |
|--|-------------|
| | |
| | |
| *************************************** | |
| | |
| THE STATE OF THE S | |
| *************************************** | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this CITROEN had different number plates. | |
| Number of plates | |
| Current registration | OK SIE |
| Plate since | |
| Current registration | NK SIE |
| Plate since | |
| | More info > |

CarCheck.co.uk page 9/12



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 10 |
| First mileage registration | 2015-09-30 |
| Last registration | 2023-06-08 |
| Complete history | See info |



| Registration #1 | 2015-09-30 | 23 mi |
|-----------------|------------|-------------------------------------|
| Registration #2 | 2018-04-27 | 45.282 mi |
| Registration #3 | 2019-04-26 | 49.206 mi |
| Registration #4 | 2020-05-21 | 52.647 mi |
| Registration #5 | 2021-05-15 | 56.451 mi |
| Registration #6 | | 111.7177 mg |
| • | | |
| Registration #7 | | 11.777 es |
| - | | 11.777 es |
| Registration #7 | | 11.777 es 11.777 es 11.777 es |

More info >

CarCheck.co.uk page 11/12



Dimensions & weight

| Width | 1895 mm |
|---------------------|---------|
| Height | 1942 mm |
| Length | 4805 mm |
| Kerb weight | 1673 kg |
| Max. allowed weight | 2661 kg |

Additional information

| Fuel tank capacity | 80 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 3 |
| Number of axles | 2 |
| Engine number | JBDF0061045 |

CarCheck.co.uk page 12/12