



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM BLUE DRIVE
Colour	Black
Year of manufacture	2016
Top speed	126 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	197 BHP
Max. torque	440 Nm at 2.750 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	46.3 mpg
Consumption combined	42.2 mpg
CO2 emission	174 g/km
CO2 label	H








Internet history

Entry 5

Date 2023-12-13

Pictures 8



source: g3remarketing.co.uk

Entry 4

Date 2023-06-14

Pictures 0

Listing price [View report](#)


source: carcraft.co.uk

Entry 3

Date 2022-04-13

Pictures 36

Listing price [View report](#)





source: yesauto.com

Entry 2

Date 2021-12-18

Pictures 36


Listing price [View report](#)



source: yesauto.com

Entry 1

Date	2021-12-09
Pictures	5
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-11
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	17
Total items failed	7

MOT #8	2023-09-12 14:01
MOT test number	550185816076
Result	✓ Passed
Next expiry date	2024-09-11

MOT #7	2023-09-06 11:53
MOT test number	650332875209
Result	✗ Failed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
Fail	Offside Front Service brake excessively fluctuating (1.2.1 (e))

MOT #6	2022-11-14 13:00
MOT test number	661629744382
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #5** 2022-11-02 15:58**MOT test number** 724459537763**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #4** 2021-10-28 10:18**MOT test number** 296080786240**Result** ✓ Passed**MOT #3** 2020-10-06 13:07**MOT test number** 282938757953**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #2 2020-10-06 07:58

MOT test number 394712801586

Result		✗ Failed
Advice	Tpms light on	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail	Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail	Nearside Front Side repeater not working (4.4.1 (a) (ii))	

MOT #1 2019-08-06 09:05

MOT test number 861446321605

Result		✓ Passed
--------	--	----------



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
11 September 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	11 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2016-07-12
Last registration	2023-09-12
Complete history	See info



Registration #1	2016-07-12	17 mi
Registration #2	2019-08-06	35.087 mi
Registration #3	2020-10-06	45.037 mi
Registration #4	2020-10-06	45.039 mi
Registration #5	2021-10-28	55.713 mi
Registration #6	2023-09-12	55.713 mi
Registration #7	2023-09-12	55.713 mi
Registration #8	2023-09-12	55.713 mi
Registration #9	2023-09-12	55.713 mi
Registration #10	2023-09-12	55.713 mi
Registration #11	2023-09-12	55.713 mi
Registration #12	2023-09-12	55.713 mi
Registration #13	2023-09-12	55.713 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	89%
Pedestrian	71%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1880 mm
Height	1675 mm
Length	4700 mm
Wheel base	2700 mm
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

D4HBGU447369