





report date: 2024-03-28

### General information

Make	VOLKSWAGEN
Model	AMAROK DC TDI DARK LABEL 4MOTION
Colour	Black
Year of manufacture	2014
Top speed	108 mph
0 - 60 mph	11.3 seconds
Gearbox	8 speed automatic

# Engine & fuel consumption

Power	178 BHP
Max. torque	420 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	38.2 mpg
Consumption combined	35.3 mpg
CO2 emission	211 g/km
CO2 label	K



CarCheck.co.uk page 1/11



report date: 2024-03-28

# Internet history

#### Entry 2


Date 2021-08-13

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date 2021-06-17

Pictures 35

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



GF64FLH report date: 2024-03-28

MOT	history
1,10,1	ilistoi y

MOT expiry date	2024-09-05
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	10
Total items failed	2

MOT #8	2023-08-11 14:14
MOT test number	509042210342
Result	<b>✓</b> Passed
Next expiry date	2024-09-05

MOT #7		2022-09-06 14:01
MOT test	number	596342127463
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	

MOT #6	2022-09-05 14:01	
MOT test number	839805772852	
Result	<b>×</b> Failed	
Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))		
Advice Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))		
Fail Central Rear Seat belt missing (7.1.2 (a))		
Advice Fluid leak, but not excessive Possibly power steering fluid (8.4.1 (a) (i))		
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))		

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #5

MOT test number

127146543258

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge N/S/F tyre wearing on inner edge (5.2.3)

(e))

MOT test number

Result

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3

MOT test number

769795507472

Result

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2 2018-09-07 10:25
MOT test number 336841573008
Result ✓ Passed

MOT #1

MOT test number

Sesult

Advice

Both of the steering rack bushes are deteriorated and have play in them

CarCheck.co.uk page 4/11



report date: 2024-03-28

#### Tax & MOT check

Tax expired: 1 March 2024





**Expires:** 5 September 2024

Tax status	Expired at 1 March 2024
Days left	60 days too late
MOT expiry date	5 September 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 5/11




report date: 2024-03-28

#### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra VOLKSWAGEN salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	
***************************************	
***************************************	
2000000	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Current registration	DIK UK
Plate since	
Current registration	NK SIK
Plate since	
	More info >

page 8/11 CarCheck.co.uk



report date: 2024-03-28

#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-10-31
Last registration	2023-08-11
Complete history	See info



Registration #1	2014-10-31	22 mi
Registration #2	2017-10-31	36.455 mi
Registration #3	2018-09-07	49.516 mi
Registration #4	2019-10-01	75.896 mi
Registration #5	2020-11-03	88.134 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.177 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

### Car features

60225	Air conditionin
60295	
50482	
60501	
60566	
60567	
60569	
iew the complete VOLKSWAGEN factory list for this vehicle	
ere.	More info >

# Safety ratings

NCAP rating	***
Adult	86%
Children	64%
Pedestrian	47%
Safety systems	57%
Overall rating	71%
Video	see crash video



# Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	CSHA093968

CarCheck.co.uk page 11/11