



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D2 R-DESIGN
Colour	Red
Year of manufacture	-
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg





Internet history

Entry 1

Date	2022-05-07
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk

**MOT history**

<b>MOT #13</b>	2022-05-09 11:28
<b>MOT test number</b>	698622346806
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-05-08

<b>MOT #12</b>	2021-10-12 14:54
<b>MOT test number</b>	969827135758
<b>Result</b>	✓ Passed

**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Rear tyre cracks

<b>MOT #11</b>	2021-10-12 08:49
<b>MOT test number</b>	692406268960
<b>Result</b>	✗ Failed

**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Rear tyre cracks

**Fail** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

**Fail** Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

<b>MOT #10</b>	2020-10-13 10:31
<b>MOT test number</b>	195577075442
<b>Result</b>	✓ Passed

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #9**

2019-10-16 11:59

**MOT test number**

243693884368

**Result**

✓ Passed

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Minor** Offside Inner Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #8**

2019-10-16 09:32

**MOT test number**

425011123485

**Result**

✗ Failed

**Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**Fail** Brake lever has insufficient reserve travel (1.1.2 (a))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #7**

2018-10-02 08:44

**MOT test number**

662302044377

**Result**

✓ Passed

**MOT #6**

2017-10-26 11:19

**MOT test number**

931774341348

**Result**

✓ Passed

**Advice** Offside Rear nail in tyre



MOT #5 2016-10-21 11:52

MOT test number 822550672281

Result ✓ Passed

- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Items removed from driver's view prior to test Camera
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

MOT #4 2015-10-28 16:49

MOT test number 281029932112

Result ✓ Passed

MOT #3 2014-10-31 13:00

MOT test number 287194904356

Result ✓ Passed

MOT #2 2014-10-31 13:00

MOT test number 445834904454

Result ✗ Failed

- Pass with rectification** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Pass with rectification** Front front brake excessively fluctuating (3.7.B.3)
- Pass with rectification** Rear brake disc in such a condition that it is seriously weakened (3.5.1i)
- Pass with rectification** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Pass with rectification** Front brake disc in such a condition that it is seriously weakened (3.5.1i)



MOT #1	2013-10-24 11:38
MOT test number	408587093264
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>AK60HYC</b>
Plate since	2024-03-28
Current registration	<b>AK60HYC</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-10-14
Last registration	2022-05-09
Complete history	<a href="#">See info</a>



Registration #1	2010-10-14	6 mi
Registration #2	2013-10-24	54.105 mi
Registration #3	2014-10-31	65.361 mi
Registration #4	2015-10-28	70.610 mi
Registration #5	2016-10-21	76.075 mi
Registration #6	2017-10-26	82.669 mi
Registration #7	2018-10-02	88.412 mi
Registration #8	2019-05-20	95.277 mi
Registration #9	2019-05-20	95.277 mi
Registration #10	2019-05-20	95.277 mi
Registration #11	2019-05-20	95.277 mi
Registration #12	2019-05-20	95.277 mi
Registration #13	2019-05-20	95.277 mi
Registration #14	2019-05-20	95.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1359 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	1361361