





report date: 2024-03-29

General information

Make	MINI
Model	MINI COOPER D
Colour	Green
Year of manufacture	2013
Top speed	116 mph
0 - 60 mph	10.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 2.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/12






report date: 2024-03-29

Internet history

Entry 1

Date	2021-06-19
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

M	$\cap T$	history
	\cup	THISLUI V

MOT expiry date	2024-06-20
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	8
Total items failed	5

MOT #11	2023-06-15 07:13
MOT test number	212781101458
Result	✓ Passed
Next expiry date	2024-06-20

MOT #10	2022-05-31 07:07
MOT test number	316547777144
Result	✓ Passed

MOT #9	2021-06-21 11:03
MOT test number	234041624420
Result	✓ Passed

MOT #8		2021-06-21 11:03
MOT test number		623514626726
Result		× Failed
Pass with rectification	Nearside Front Road wheel fixing missing (5.2.1 (a) (i))	

CarCheck.co.uk page 3/12



MF13UWA
report date: 2024-03-29

MOT #7 2021-02-15 11:47

MOT test number 731273692073

Advice Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

MOT #6 2020-02-06 11:22

MOT test number 225371711063

Result \(\sqrt{Passed} \)

MOT #5 2018-02-19 11:30

MOT test number 679613571690

Result \rightarrow Passed

MOT #4 2018-02-16 17:00

MOT test number 902263488282

Result X Failed

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #3 2017-05-18 15:31

MOT test number 909545354257

Result ✓ Passed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice No acceleration detected

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT test number

Result

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice No acceleration detected

 MOT #1
 2016-04-13 09:50

 MOT test number
 479322242436

 Result
 ✓ Passed

CarCheck.co.uk page 5/12





Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	20 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>l</u>	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	NIK NIK
Plate since	
Current registration	IK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12





report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-05-11
Last registration	2023-06-15
Complete history	See info



Registration #1	2013-05-11	16 mi
Registration #2	2016-04-13	32.693 mi
Registration #3	2017-05-18	41.865 mi
Registration #4	2017-05-18	41.865 mi
Registration #5	2018-02-16	46.134 mi
Registration #6	2018-02-19	46.134 mi
Registration #7	2020-02-06	74.962 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		10.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1996 mm
Height	1518 mm
Length	4109 mm
Wheel base	2596 mm
Kerb weight	1300 kg
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity	47
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/1