





General information

Make	VAUXHALL
Model	VIVA SL
Colour	White
Year of manufacture	2017
Top speed	106 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	95 Nm at 4.500 rpm
Engine capacity	999 сс
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	104 g/km
CO2 label	В







Internet history

Entry 1	
Date	2021-10-13
Pictures	30
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-29
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	15
Total items failed	2

MOT #7	2023-11-27 13:57
MOT test number	263384520216
Result	✓ Passed
Next expiry date	2024-11-29

МОТ #6	2022-11-23 10:52
MOT test number	848235968515
Result	✓ Passed

MOT #5	2021-11-10 14:10
MOT test number	761042568764
Result	✓ Passed

МОТ #4	2021-11-10 11:15
MOT test number	346249731955
Result	🗙 Failed
Fail Registration plate incorrect registration number is incorrect (0.1 (c))	





MOT #3		2020-11-11 09:58
MOT test	number	608362226218
Result		✓ Passed
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #2		2020-11-11 09:58
MOT test	number	851600779133
Result		× Failed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Pass with (h))	th rectification Tyre pressure monitoring system malfunctioning or obvio	usly inoperative (5.2.3
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	





MOT #1	2020-05-22 06:45
MOT test number	246441575752
Result	✓ Passed
Advice COVID-19 6 MONTH EXTENSION	



RA17OYV report date: 2024-03-28

Tax & MOT check

✓ Taxed	✓ MOT
Tax due: 1 May 2024	Expires: 29 November 2024
Tax status	Valid until 1 May
Days left	3
MOT expiry date	29 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FET O
Category	APMP
Туре	
Damage 2	AMPLE
Date	
Category	AMPL
Туре	

Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	₩ UK
Ender class	





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-05-30
Last registration	2023-11-27
Complete history	See info



Registration #1	2017-05-30	16 mi
Registration #2	2020-11-11	47.673 mi
Registration #3	2020-11-11	47.673 mi
Registration #4		11.777 est
Registration #5		11.777 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.317 esi





Safety ratings

NCAP rating	****	
Adult	52%	TEURO
Children	91%	
Pedestrian	53%	
Safety systems	57%	Lange Lange
Overall rating	61%	
Video	see crash video	

Dimensions & weight	
Width	1876 mm
Height	1485 mm
Length	3675 mm
Wheel base	2385 mm
Kerb weight	864 kg
Max. allowed weight	1353 kg
Additional information	
Additional information Fuel tank capacity	32 l
	32 I Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 5