





General information

Make	RENAULT
Model	KANGOO ML19 DCI
Colour	White
Year of manufacture	2011
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP	0 < 101 A
Engine capacity	1.461 cc	101 - 120 ^B
Cylinders	4	121 - 140 P
Fuel type	Diesel	141 - 165 F
Consumption combined	54.3 mpg	166 - 185
		196 005

225+





Internet history

Entry 1	
Date	

2022-02-11

21

Listing price

Pictures

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-25
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	12
Total items failed	6

MOT #13	2023-10-26 15:25
MOT test number	451171327182
Result	Passed
Next expiry date	2024-10-25
Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #12	2022-12-15 10:06
MOT test number	389178592286
Result	✓ Passed
AdviceNearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))AdviceNearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #11	2022-01-12 13:39
MOT test number	231231044846
Result	✓ Passed





MOT #10	2022-01-12 11:48
MOT test number	941303774723
Result	🗙 Failed
Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
MOT #9	2021-02-04 15:16
MOT test number	749157432772
Result	Passed
MOT #8	2021-02-04 08:53
MOT test number	545091022280
Result	🗙 Failed
Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
MOT #7	2020-02-04 10:03
MOT test number	119118450965
Result	✓ Passed
Advice Nearside Oil leak, but not excessive Inner drive shaft seal weeping (8)	(1, (2), (3))

Advice Nearside Oil leak, but not excessive Inner drive shaft seal weeping (8.4.1 (a) (i))
Advice Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened Inner face (1.1.14 (a)

MOT #6	2019-02-13 17:20
MOT test number	617688800572
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge Worn on outer edge (5.2.3 (e))	

(ii))





MOT #5	2019-02-12 12:34
MOT test number	968371423375
Result	🗙 Failed
Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Minor Offside Registration plate lamp inoperative in the case of multiple lamps (i))	or light sources (4.7.1 (b)
Fail Nearside Outer Drive shaft joint constant velocity boot split or insecure, no ingress of dirt (6.1.7 (g) (ii))	longer prevents the
Advice Nearside Front Tyre worn close to legal limit/worn on edge Worn on out	er edge (5.2.3 (e))
Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail Offside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))	


MOT #4	2018-02-14 16:11
MOT test number	457272932652
Result	✓ Passed

MOT #3	2016-12-01 11:26
MOT test number	587168104305
Result	✓ Passed
Advice Nearside Rear Nail in tyre	
MOT #2	2015-11-25 11:46
MOT test number	938202019811
Result	✓ Passed
NOT #1	2014 12 12 10 20

MOT #1	2014-12-13 10:20
MOT test number	838847844301
Result	✓ Passed



Tax & MOT check







Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra RENAULT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

NUMBER OF TAXABLE	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-12-16
Last registration	2023-10-26
Complete history	<u>See info</u>



Registration #1	2011-12-16	18 mi
Registration #2	2014-12-13	48.521 mi
Registration #3	2015-11-25	66.126 mi
Registration #4	2016-12-01	79.739 mi
Registration #5	2018-02-14	96.958 mi
Registration #6	2019-02-12	130.164 mi
Registration #7	2019-02-13	130.164 mi
Registration #8	2020-02-04	143.270 mi
Registration #9		11.777 mi
Registration #10		11.777 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 est
Registration #15		11.117 esi





Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
S0566	
\$0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1829 mm
Height	1809 mm
Length	4213 mm
Kerb weight	1261 kg
Max. allowed weight	1936 kg
Additional information	
Fuel delivery	Direct Injection
Number of doors	3

2

D035207

Number of seats

Engine number