





General information

| Make | LAND ROVER |
|---------------------|-------------------|
| Model | FREELANDER SD4 GS |
| Colour | Black |
| Year of manufacture | 2014 |
| Top speed | 118 mph |
| 0 - 100 km/h | 9.5 seconds |
| 0 - 60 mph | 8.7 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 140 kW / 191 HP / 190 BHP |
|-------------------------|---------------------------|
| Max. torque | 420 Nm at 1.750 rpm |
| Engine capacity | 2.179 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 32.5 mpg |
| Consumption extra urban | 48.7 mpg |
| Consumption combined | 40.4 mpg |
| CO2 emission | 185 g/km |
| CO2 label | I |







Internet history

| Entry 2 | |
|---------------|--------------------|
| Date | 2021-09-11 |
| Pictures | 50 |
| Listing price | <u>View report</u> |



source: cargurus.co.uk

Entry 1

Date

Pictures

Listing price

2021-09-09 58

50

View report



source: autotrader.co.uk









MOT history

| MOT expiry date | 2024-09-07 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 8 |
| Failed MOT tests | 0 |
| Total advice items | 6 |
| Total items failed | 0 |

| MOT #8 | 2023-09-05 07:57 |
|-----------------------------------------------------------------------------------|------------------|
| MOT test number | 192214007862 |
| Result | Passed |
| Next expiry date | 2024-09-07 |
| Advice Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii)) | |

| MOT #7 | 2022-08-18 13:49 |
|-----------------|------------------|
| MOT test number | 928519489876 |
| Result | ✓ Passed |
| | |
| МОТ #6 | 2021-09-08 15:48 |
| MOT test number | 627436592242 |
| Result | ✓ Passed |
| | |
| MOT #5 | 2021-01-11 13:54 |
| MOT test number | 957939040002 |
| Result | ✓ Passed |





| MOT #4 | | 2020-01-20 14:51 |
|----------|---------------------------------------------------------------------------------|------------------|
| MOT test | number | 126976492479 |
| Result | | ✓ Passed |
| Advice | Front Tyre worn close to legal limit/worn on edge both fronts 3.5mm (5.2.3 (e)) | |
| Minor | Offside Obligatory mirror slightly damaged wing mirror cracked (3.3 (b) (i)) | |
| Advice | Rear Tyre worn close to legal limit/worn on edge both rears on wear markers (5. | 2.3 (e)) |

| MOT #3 | 2019-01-10 14:03 |
|----------------------------------------------------------------|------------------|
| MOT test number | 102951604736 |
| Result | ✓ Passed |
| Minor Offside Obligatory mirror slightly damaged (3.3 (b) (i)) | |

| MOT #2 | | 2018-01-15 14:22 |
|----------------------------------------------------------------------------------------------|--|------------------|
| MOT test number | | 390083507739 |
| Result | | ✓ Passed |
| Advice Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a) | | |

| MOT #1 | 2017-01-10 14:38 |
|-----------------|------------------|
| MOT test number | 990984026188 |
| Result | ✓ Passed |



Tax & MOT check

| ✓ Taxed | √ МОТ |
|---------------------------------|-------------------------------------|
| Tax due: 1 April 2025 | Expires: 7 September 2024 |
| Tax status | Valid until 1 April |
| Days left | 338 |
| MOT expiry date | 7 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|-----------------------------------------|------------|
| Band | I |
| Single payment (12 months) | £ 320,00,- |
| Single six month payment | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |





Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-----------|
| Date | FE C |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPLE |
| Date | 4 |
| Category | AMPLI |
| Туре | W CON |

Extra LAND ROVER salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| | More info | > |
|-------------------------------------------------------------------|-----------|---|
| | | · |
| Plate changes | | |
| See in this check if this LAND ROVER had different number plates. | | |

| Number of plates | , |
|----------------------|-------------|
| Current registration | |
| Plate since | 1000-20-20 |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 11 |
| First mileage registration | 2014-01-09 |
| Last registration | 2023-09-05 |
| Complete history | <u>See info</u> |



| Registration #1 | 2014-01-09 | 28 mi |
|------------------------------------|------------|----------------------------------------|
| Registration #2 | 2017-01-10 | 25.324 mi |
| Registration #3 | 2018-01-15 | 32.563 mi |
| Registration #4 | 2019-01-10 | 42.110 mi |
| Registration #5 | 2020-01-20 | 52.652 mi |
| Registration #6 | 2021-01-11 | 57.100 mi |
| Registration #7 | | 10.317 mil |
| | | |
| Registration #8 | | 11.577 est |
| Registration #8 Registration #9 | | 11.577 es |
| | | 11.577 est 11.577 est 11.577 est |





Safety ratings

NCAP rating

Video

see crash video



| Dimensions & weight | |
|-------------------------------------------|--------------------------|
| Width | 2005 mm |
| Height | 1740 mm |
| Length | 4500 mm |
| Wheel base | 2660 mm |
| Kerb weight | 1745 kg |
| Max. allowed weight | 2505 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 68 l |
| | 68 l Direct Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Direct Injection |