




report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D5 SE SPORT
Colour	Blue
Year of manufacture	2008
Top speed	134 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.2 mpg
CO2 emission	195 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-08-19
Pictures	50
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-18
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	35
Total items failed	9

MOT #20	2023-07-25 11:06
MOT test number	651366790757
Result	✓ Passed
Next expiry date	2024-08-18
Advice	Nearside Side repeater slightly discoloured (4.4.3 (a))
Advice	Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #19	2023-07-19 09:58
MOT test number	641371084550
Result	✗ Failed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Side repeater slightly discoloured (4.4.3 (a))
Advice	Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
Fail	Nearside Front Road wheel badly distorted (5.2.2 (c) (i))

**MOT #18**

2022-07-26 09:11

MOT test number

971509420654

Result

✓ Passed

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge edge wearing and general wear @3/3.5mm (limit 1.6mm) (5.2.3 (e))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm main support mounting (5.3.4 (a) (i))**MOT #17**

2021-08-19 11:00

MOT test number

858709162341

Result

✓ Passed

MOT #16

2021-08-18 15:23

MOT test number

307055489867

Result

✗ Failed

Fail Nearside Front Tyre tread depth below requirements of 1.6mm Worn On Edges (5.2.3 (e))**MOT #15**

2021-08-18 15:21

MOT test number

395757750811

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge Edges (5.2.3 (e))

**MOT #14**

2020-09-04 14:08

MOT test number

319545960521

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge Wearing inner edge (5.2.3 (e))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Wearing outer edge (5.2.3 (e))
- Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #13

2019-03-13 17:28

MOT test number

887039139295

Result

✓ Passed

- Advice** Damage to front panel
- Advice** Repair effected to nearside side repeater lens
- Advice** Damage to nearside front tyre outer sidewall

MOT #12

2019-03-13 10:46

MOT test number

854171729222

Result

✗ Failed

- Advice** Damage to nearside front tyre outer sidewall
- Advice** Nearside Front amber position/corner lamp inoperative
- Fail** Nearside Front Position lamp not working (4.2.1 (a))
- Advice** Damage to front panel
- Advice** Repair effected to nearside side repeater lens
- Fail** Nearside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #11** 2018-03-28 09:39**MOT test number** 954244245586**Result** ✓ Passed**Advice** Nearside Rear Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #10** 2017-04-12 15:38**MOT test number** 460568890839**Result** ✓ Passed**MOT #9** 2017-04-12 11:12**MOT test number** 648003646669**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm due to inner tread pattern distorted and under 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #8** 2016-04-11 15:10**MOT test number** 878413018211**Result** ✓ Passed**MOT #7** 2015-04-13 11:16**MOT test number** 889543605145**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #6** 2015-04-13 11:16**MOT test number** 288513105151**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Engine covers fitted obscuring some components in the engine bay**Pass with rectification** Nearside Headlamp aim too high (1.8)**Notice** Under-trays fitted obscuring some underside components**MOT #5** 2014-03-31 08:03**MOT test number** 525850894059**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #4** 2013-04-10 15:07**MOT test number** 955680203103**Result** ✓ Passed**Notice** Nearside front wheel badly buckled .**MOT #3** 2012-04-24 14:36**MOT test number** 285335812180**Result** ✓ Passed



MOT #2	2012-04-24 14:36
MOT test number	177465212128
Result	✗ Failed
Pass with rectification	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Pass with rectification	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1	2011-05-06 15:17
MOT test number	577666821183
Result	✓ Passed
Notice	Emissions to low



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
18 August 2024

Tax status	Valid until 1 May
Days left	367
MOT expiry date	18 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history


Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	RK08XMS
Plate since	2024-03-29
Current registration	RK08XMS
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-05-15
Last registration	2023-07-25
Complete history	See info



Registration #1	2008-05-15	14 mi
Registration #2	2011-05-06	26.597 mi
Registration #3	2012-04-24	34.424 mi
Registration #4	2013-04-10	40.333 mi
Registration #5	2014-03-31	48.471 mi
Registration #6	2015-04-13	59.233 mi
Registration #7	2016-04-11	70.590 mi
Registration #8	2017-04-12	79.671 mi
Registration #9	2017-04-12	79.671 mi
Registration #10	2018-03-28	88.580 mi
Registration #11	2019-05-20	95.377 mi
Registration #12	2019-05-20	95.377 mi
Registration #13	2019-05-20	95.377 mi
Registration #14	2019-05-20	95.377 mi
Registration #15	2019-05-20	95.377 mi
Registration #16	2019-05-20	95.377 mi
Registration #17	2019-05-20	95.377 mi
Registration #18	2019-05-20	95.377 mi
Registration #19	2019-05-20	95.377 mi
Registration #20	2019-05-20	95.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1778 kg
Max. allowed weight	2310 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	560100