



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	MATRIX GSI
Colour	Red
Year of manufacture	2008
Top speed	105 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	141 Nm at 4.500 rpm
Engine capacity	1.599 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	42.8 mpg
Consumption combined	35.3 mpg
CO2 emission	174 g/km
CO2 label	H






Internet history

Entry 1

Date	2022-03-17
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-04
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	27
Total items failed	7

MOT #17	2023-09-20 12:56
MOT test number	677819143059
Result	✓ Passed
Next expiry date	2024-10-04

MOT #16	2022-10-05 10:43
MOT test number	348925285442
Result	✓ Passed
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #15	2022-10-05 10:43
MOT test number	364415005794
Result	✗ Failed
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Pass with rectification	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #14	2022-03-15 13:35
MOT test number	943798507464
Result	✓ Passed

**MOT #13** 2021-04-29 13:36**MOT test number** 458796734863**Result** ✓ Passed**MOT #12** 2020-05-13 10:51**MOT test number** 494713821441**Result** ✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge edges (5.2.3 (e))

MOT #11 2020-05-13 09:19**MOT test number** 859863474350**Result** ✗ Failed

- MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge edges (5.2.3 (e))
- DANGEROUS** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #10**

2019-04-15 14:52

MOT test number

793185319905

Result

✓ Passed

Minor

Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice

Nearside Rear tyre cracking on inner and outer walls

Minor

Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #9

2018-04-25 15:12

MOT test number

878334339002

Result

✓ Passed

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #8

2018-04-25 11:15

MOT test number

509293605423

Result

✗ Failed

Fail

Front registration plate deteriorated (6.3.1d)

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Fail

Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords inner & outer edges (4.1.D.1a)

Fail

Supplementary Restraint System warning lamp indicates a fault (5.4.2)

Fail

Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #7** 2017-04-22 08:50**MOT test number** 306202996634**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Nearside rear tyre tread surface slightly deteriorated**Advice** Supplementary Restraint System warning lamp does not illuminate (5.4.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2016-04-30 10:08**MOT test number** 955670788742**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-04-14 10:37**MOT test number** 708244405110**Result** ✓ Passed**Notice** Nearside rear tyre has slight cracks on tread**Advice** Offside Front constant velocity joint is slightly worn (2.5.C.1b)**MOT #4** 2014-04-05 11:26**MOT test number** 998475094032**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-01-12 10:45**MOT test number** 536012013072**Result** ✓ Passed



MOT #2	2013-01-12 10:01
MOT test number	818662013018
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Offside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #1	2012-01-13 08:43
MOT test number	157733512026
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
4 October 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	4 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history


Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	NX58YZD
Plate since	2019-03-29
Current registration	NX58YZD
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-09-01
Last registration	2023-09-20
Complete history	See info



Registration #1	2008-09-01	12 mi
Registration #2	2012-01-13	22.450 mi
Registration #3	2013-01-12	33.738 mi
Registration #4	2013-01-12	33.738 mi
Registration #5	2014-04-05	47.471 mi
Registration #6	2015-04-14	51.012 mi
Registration #7	2016-04-30	54.308 mi
Registration #8	2017-04-22	57.620 mi
Registration #9	2018-04-25	60.360 mi
Registration #10	2018-04-25	60.366 mi
Registration #11	2019-05-20	60.377 mi
Registration #12	2019-05-20	60.377 mi
Registration #13	2019-05-20	60.377 mi
Registration #14	2019-05-20	60.377 mi
Registration #15	2019-05-20	60.377 mi
Registration #16	2019-05-20	60.377 mi
Registration #17	2019-05-20	60.377 mi
Registration #18	2019-05-20	60.377 mi
Registration #19	2019-05-20	60.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1740 mm
Height	1625 mm
Length	4025 mm
Wheel base	2600 mm
Kerb weight	1327 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	G4ED7T013093