



report date: 2024-03-29

General information

Make	FIAT
Model	DOBLO JTD DYNAMIC (120BHP)
Colour	Grey
Year of manufacture	2007
Top speed	110 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	210 Nm at 3.000 rpm
Engine capacity	1.910 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-04
Pictures	11
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-04-22
MOT pass rate	61 %
MOT passed	14
Failed MOT tests	9
Total advice items	64
Total items failed	14

MOT #23	2024-04-23 15:27
MOT test number	244981271383
Result	✓ Passed
Next expiry date	2025-04-22

MOT #22	2024-04-23 14:00
MOT test number	121049675340
Result	✗ Failed
MAJOR	Offside Rear Direction indicator not working (4.4.1 (a) (ii))
MAJOR	Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))
MAJOR	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #21	2023-03-31 10:37
MOT test number	369916025908
Result	✓ Passed

MOT #20	2023-03-31 08:35
MOT test number	501872686881
Result	✗ Failed
MAJOR	Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
Advice	Tyre worn close to legal limit/worn on edge both front on edges (5.2.3 (e))

**MOT #19** 2022-04-21 10:20**MOT test number** 290078221694**Result** ✓ Passed**Advice** Rear Shock absorbers has a slightly worn bush both (5.3.2 (c))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Inner Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**MOT #18** 2022-04-19 15:25**MOT test number** 123923020626**Result** ✗ Failed**DANGEROUS** Exhaust emits excessive smoke or vapour likely to obscure the vision of other road users (8.2.2.2 (c))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Shock absorbers has a slightly worn bush both (5.3.2 (c))**Advice** Front Inner Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**MAJOR** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #17** 2021-04-20 15:35**MOT test number** 658958643918**Result** ✓ Passed**MOT #16** 2019-05-15 10:47**MOT test number** 708708273909**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #15**

2018-05-16 08:48

MOT test number

333278677521

Result

✓ Passed

- Advice** Oil leak
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened heavily corroded on inner surface (3.5.1i)
- Advice** Offside Rear Tyre worn close to the legal limit tyre on 2mm & perished (4.1.E.1)
- Advice** Drivers door stay hinge broken
- Advice** Boot lid supporting struts weak
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Tyre worn close to the legal limit tyre on 3mm & perished (4.1.E.1)
- Advice** Engine management light on - engine failure message displayed
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Rear exhaust box rubber hangers very heavily perished

MOT #14

2017-05-18 09:03

MOT test number

663422731413

Result

✓ Passed

- Advice** Nearside Front brake pad wear sensor wire broken
- Advice** Offside Front tyre worn on inner edge

MOT #13

2016-05-26 15:02

MOT test number

434176862319

Result

✓ Passed

- Advice** Rear exhaust mounting rubber split/perished

**MOT #12** 2016-05-26 09:58**MOT test number** 535604563665**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit 2.2mm and worn on both edges (4.1.E.1)**Advice** Rear exhaust mounting rubber split/perished**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front brake pad wear sensor wire broken**MOT #11** 2015-05-07 10:12**MOT test number** 396317525195**Result** ✓ Passed**Notice** Unable to check rear seat belts due to seats stowed away**Notice** Under-trays fitted obscuring some underside components**Notice** Undrtray loose**MOT #10** 2015-05-06 09:39**MOT test number** 979496825124**Result** ✗ Failed**Notice** Undrtray loose**Fail** Headlamp aim too high (1.8)**Fail** Offside Rear Shock absorber has an excessively worn bush (2.7.4)**Notice** Unable to check rear seat belts due to seats stowed away**Fail** Battery insecure (1.9.1)**Notice** Under-trays fitted obscuring some underside components**Fail** Nearside Rear Shock absorber has an excessively worn bush (2.7.4)

**MOT #9** 2014-06-02 13:15**MOT test number** 236583854417**Result** ✓ Passed**Notice** Exhaust corroded**MOT #8** 2014-06-02 13:15**MOT test number** 556763454184**Result** ✗ Failed**Notice** Exhaust corroded**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #7** 2013-05-24 16:22**MOT test number** 207744443148**Result** ✓ Passed**Notice** Play in steering rack at nearside**Notice** Drivers door strap broken**MOT #6** 2013-05-24 08:51**MOT test number** 496224443150**Result** ✗ Failed**Notice** Rear silencer bracket, condition**Fail** Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Play in steering rack at nearside**Notice** Drivers door strap broken**MOT #5** 2012-05-26 10:12**MOT test number** 426227642155**Result** ✓ Passed

**MOT #4** 2012-05-26 08:55**MOT test number** 398677542160**Result** ✗ Failed**Fail** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Rear Exhaust system not adequately supported (7.1.1)**MOT #3** 2011-05-27 17:11**MOT test number** 298977741400**Result** ✓ Passed**Notice** Rear tyres perished and splitting**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Nearside front washer jet partially blocked**Notice** Front brakes binding slightly**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #2** 2011-05-27 11:39**MOT test number** 718347941145**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Notice** Front brakes binding slightly**Fail** Exhaust tailpipe not capable of allowing the emission probe to be inserted (7.4.B.1)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Nearside front washer jet partially blocked**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Vehicle undertray loose**Fail** Rear Exhaust has a part missing (7.1.1a)**Fail** Emissions not tested (7.0)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Rear tyres perished and splitting**MOT #1** 2010-06-29 10:12**MOT test number** 624140780101**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Both rear tyres wearing unevenly**Notice** Rear foot brake imbalance exceeds 25%, possible service/adjustment required? (park brake balance is ok)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Rear wiper blade u/s**Notice** Heavy wear ridge on front discs



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
22 April 2025

Tax status	Valid until 1 October
Days left	154
MOT expiry date	22 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2007-01-31
Last registration	2024-04-23
Complete history	See info



Registration #1	2007-01-31	16 mi
Registration #2	2010-06-29	37.807 mi
Registration #3	2011-05-27	44.728 mi
Registration #4	2011-05-27	44.728 mi
Registration #5	2012-05-26	52.912 mi
Registration #6	2012-05-26	52.912 mi
Registration #7	2013-05-24	64.254 mi
Registration #8	2013-05-24	64.254 mi
Registration #9	2014-06-02	73.631 mi
Registration #10	2015-05-06	80.243 mi
Registration #11	2015-05-07	80.243 mi
Registration #12	2016-05-26	90.666 mi
Registration #13	2016-05-26	90.666 mi
Registration #14	2016-05-26	90.666 mi
Registration #15	2016-05-26	90.666 mi
Registration #16	2016-05-26	90.666 mi
Registration #17	2016-05-26	90.666 mi
Registration #18	2016-05-26	90.666 mi
Registration #19	2016-05-26	90.666 mi
Registration #20	2016-05-26	90.666 mi
Registration #21	2016-05-26	90.666 mi
Registration #22	2016-05-26	90.666 mi
Registration #23	2016-05-26	90.666 mi
Registration #24	2016-05-26	90.666 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1722 mm
Height	1818 mm
Length	4253 mm
Wheel base	2583 mm
Kerb weight	1320 kg
Max. allowed weight	3240 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	5504986