





General information

| Make | VAUXHALL |
|---------------------|-------------------|
| Model | CASCADA ELITE S/S |
| Colour | Grey |
| Year of manufacture | 2015 |
| Top speed | 129 mph |
| 0 - 60 mph | 10.2 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 140 BHP |
|-------------------------|---------------------|
| Max. torque | 200 Nm at 1.850 rpm |
| Engine capacity | 1.364 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 36.2 mpg |
| Consumption extra urban | 52.3 mpg |
| Consumption combined | 44.8 mpg |
| CO2 emission | 148 g/km |
| CO2 label | F |







| Internet history | |
|------------------|-------------|
| Entry 1 | |
| Date | 2021-02-05 |
| Pictures | 0 |
| Listing price | View report |

source: autoonline.co.uk



MOT history

| MOT expiry date | 2024-05-29 |
|--------------------|------------|
| MOT pass rate | 86 % |
| MOT passed | 6 |
| Failed MOT tests | 1 |
| Total advice items | 5 |
| Total items failed | 2 |

| MOT #7 | 2023-05-20 09:17 |
|--|------------------|
| MOT test number | 221729960822 |
| Result | ✓ Passed |
| Next expiry date | 2024-05-29 |
| Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b)) | |

| MOT #6 | | 2022-05-30 15:29 |
|----------|--|------------------|
| MOT test | number | 562016527941 |
| Result | | ✓ Passed |
| Advice | Nearside Front Shock absorbers has light misting of oil (5.3.2 (b)) | |
| Advice | Fluid leak, but not excessive coolant loss from thermostat housing (8.4.1 (a) (i)) | |

| MOT #5 | 2022-05-30 09:44 |
|---|------------------|
| MOT test number | 977748567198 |
| Result | 🗙 Failed |
| Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i)) | |
| Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b)) | |
| FailOffside Rear Coil spring fractured or broken (5.3.1 (b) (i)) | |
| Advice Fluid leak, but not excessive coolant loss from thermostat housing (8.4.1 (a) (i)) | |





| MOT #4 | 2021-05-25 11:03 |
|-----------------|------------------|
| MOT test number | 208053676126 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2020-09-11 14:40 |
| MOT test number | 129603310872 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2019-06-25 16:18 |
| MOT test number | 499467902323 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2018-06-23 11:09 |
| MOT test number | 779205345770 |
| Result | ✓ Passed |



Tax & MOT check

| ✓ Taxed | мот |
|------------------------|-------------------------|
| Tax due: 1 May 2024 | Expires: 29 May 2024 |
| Tax status | Valid until 1 May |
| Days left | 2 |
| MOT expiry date | 29 May 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | F |
| Single payment (12 months) | £ 200,00,- |
| Single six month payment | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---------|
| Date | FE CO |
| Category | A RINPE |
| Туре | |
| Damage 2 | AMPLE |
| Date | 4 |
| Category | AMPLI |
| Туре | W SCO |

Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ******** | |
|---|-------------|
| | |
| | |
| *********** | |
| ********* | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this VAUXHALL had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Current registration | ₩ UK |
| Ender class | |
| | |





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 9 |
| First mileage registration | 2015-06-25 |
| Last registration | 2023-05-20 |
| Complete history | <u>See info</u> |



| Registration #1 | 2015-06-25 | 28 mi |
|-----------------|------------|------------|
| Registration #2 | 2018-06-23 | 39.006 mi |
| Registration #3 | 2019-06-25 | 47.326 mi |
| Registration #4 | 2020-09-11 | 54.657 mi |
| Registration #5 | | 11.777 mi |
| Registration #6 | | 11.777 esi |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 11.777 est |
| Registration #9 | | 11.777 esi |

More info >





Safety ratings

| NCAP rating | **** | ۲ |
|----------------|-----------------|------------|
| Adult | 87% | S . |
| Children | 72% | |
| Pedestrian | 65% | |
| Safety systems | 81% | / |
| Overall rating | 79% | - |
| Video | see crash video | |



| Dimensions & weight | |
|--|-------------------------------|
| Width | 2020 mm |
| Height | 1443 mm |
| Length | 4696 mm |
| Wheel base | 2695 mm |
| Kerb weight | 1626 kg |
| Max. allowed weight | 2110 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 56 I |
| | 56 l Multi-Point Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Multi-Point Injection |
| Fuel tank capacity Fuel delivery Number of doors | Multi-Point Injection 2 |