



report date: 2024-03-28

General information

Make	NISSAN
Model	PIXO N-TEC
Colour	Grey
Year of manufacture	2009
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	B





Internet history

Entry 1

Date	2022-07-05
Pictures	1
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-11-02
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	22
Total items failed	2

MOT #14 2023-11-03 13:40

MOT test number 392695646147

Result ✓ Passed

Next expiry date 2024-11-02

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge + perishing/cracking (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing + nail (5.2.3 (d) (ii))
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #13 2022-09-29 08:49

MOT test number 351856147512

Result ✓ Passed

MOT #12 2022-09-28 14:02

MOT test number 371821309220

Result ✗ Failed

- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #11**

2021-09-03 10:21

**MOT test number**

211656055005

**Result**

✓ Passed

**Advice** Tyres starting to perish**Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #10**

2020-09-10 14:03

**MOT test number**

966110254004

**Result**

✓ Passed

**Advice** Nearside Rear Nail in tyre**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #9**

2019-09-12 15:28

**MOT test number**

568707751624

**Result**

✓ Passed

**Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**MOT #8**

2018-09-11 15:03

**MOT test number**

217724843192

**Result**

✓ Passed

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #7** 2018-09-11 11:00**MOT test number** 453227489723**Result** ✗ Failed**Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Offside Headlamp has a product on the light source so that the light output is severely reduced (4.1.4 (b))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**MOT #6** 2017-09-07 12:20**MOT test number** 984901891896**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear tyre heavily perished**Advice** Nearside Rear tyre heavily perished**Advice** Offside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #5** 2016-09-13 14:27**MOT test number** 882957611735**Result** ✓ Passed**MOT #4** 2015-09-04 11:14**MOT test number** 559366286442**Result** ✓ Passed**MOT #3** 2014-09-09 15:24**MOT test number** 825032654287**Result** ✓ Passed



MOT #2	2013-09-09 12:02
MOT test number	586102753250
Result	✓ Passed
Notice	Offside front tyre tread low on very outer edge.
Advice	Offside Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)

MOT #1	2012-08-30 15:11
MOT test number	419643542226
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
2 November 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	248
<b>MOT expiry date</b>	2 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-09-12
Last registration	2023-11-03
Complete history	<a href="#">See info</a>



Registration #1	2009-09-12	22 mi
Registration #2	2012-08-30	6.970 mi
Registration #3	2013-09-09	9.610 mi
Registration #4	2014-09-09	12.939 mi
Registration #5	2015-09-04	15.981 mi
Registration #6	2016-09-13	18.577 mi
Registration #7	2017-09-07	21.474 mi
Registration #8	2018-09-11	24.435 mi
Registration #9	2019-09-09	25.377 mi
Registration #10	2020-09-09	25.377 mi
Registration #11	2021-09-09	25.377 mi
Registration #12	2022-09-09	25.377 mi
Registration #13	2023-09-09	25.377 mi
Registration #14	2024-09-09	25.377 mi
Registration #15	2025-09-09	25.377 mi
Registration #16	2026-09-09	25.377 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	107462