



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM
Colour	Black
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	194 BHP
Max. torque	422 Nm at 1.900 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	50.4 mpg
Consumption combined	41.5 mpg
CO2 emission	176 g/km
CO2 label	I






Internet history

Entry 3

Date	2022-02-14
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

Entry 2

Date	2022-01-31
Pictures	20
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-10-23
Pictures	11
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-01-25
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	45
Total items failed	11

MOT #16	2024-01-26 14:51
MOT test number	752298778777
Result	✓ Passed
Next expiry date	2025-01-25

MOT #15	2023-03-28 08:12
MOT test number	435689492875
Result	✓ Passed
Minor	Nearside Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #14	2022-04-06 07:29
MOT test number	669747293908
Result	✓ Passed
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13**

2022-03-31 14:29

MOT test number

888072382620

Result**✗ Failed****Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Seat belt buckle not functioning as intended 2nd seat row (7.1.2 (d))**Fail** Offside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #12**

2021-08-20 14:58

MOT test number

511472795034

Result**✓ Passed****Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Parking brake has slight reserve travel.**Advice** Rear Tyre worn close to legal limit/worn on edge Both inner edge. (5.2.3 (e))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**Minor** Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt Both. (2.1.3 (g) (i))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Slight surface rust underneath.

**MOT #11**

2020-08-22 10:32

MOT test number

516445711491

Result

✓ Passed

- Advice** Offside Front tyre wearing inner edge
- Advice** Offside Rear Nail in tyre
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Under tray fitted
- Advice** Offside Rear tyre wearing inner edge
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #10

2020-08-07 09:56

MOT test number

344048994209

Result

✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Side repeater not working (4.4.1 (a) (ii))
- Advice** Offside Rear Nail in tyre
- Advice** Parking brake performance only just met requires adjustment to shoes
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #9

2019-08-09 09:20

MOT test number

360142516367

Result

✓ Passed



MOT #8	2018-10-26 08:39
MOT test number	297353420665
Result	✓ Passed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #7	2018-10-25 11:20
MOT test number	216391797588
Result	✗ Failed
Fail	Offside Rear Seat belt buckle not functioning as intended (7.1.2 (d))
Fail	Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Fail	Offside Front Side repeater lens defective such that the emitted light is adversely affected (4.4.1 (b) (ii))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #6	2017-10-19 09:32
MOT test number	178780921469
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**MOT #5** 2017-10-18 12:46**MOT test number** 305741977582**Result** ✗ Failed**Fail** Front Service brake juddering severely steering wheel shaking (3.7.C.2)**Advice** Offside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2016-10-26 13:29**MOT test number** 559642697209**Result** ✓ Passed**MOT #3** 2016-10-24 16:26**MOT test number** 384954871676**Result** ✗ Failed**Fail** Nearside Front Side repeater not working door (1.4.A.2c)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #2** 2015-10-06 12:04**MOT test number** 192196848569**Result** ✓ Passed



MOT #12015-09-25 10:25

MOT test number334519622416

Result

Failed

- Advice

Front Brake pad(s) wearing thin (3.5.1g)
- Advice

Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement front (2.4.G.2)
- Advice

Rear Brake pad(s) wearing thin (3.5.1g)
- Fail

Nearside Front Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
25 January 2025

Tax status	Valid until 1 July
Days left	62
MOT expiry date	25 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	ST62FJZ
Plate since	2019-03-29
Current registration	ST62FJZ
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2012-10-25
Last registration	2024-01-26
Complete history	See info



Registration #1	2012-10-25	27 mi
Registration #2	2015-09-25	44.820 mi
Registration #3	2015-10-06	44.975 mi
Registration #4	2016-10-24	55.171 mi
Registration #5	2016-10-26	55.172 mi
Registration #6	2017-10-18	61.788 mi
Registration #7	2017-10-19	61.791 mi
Registration #8	2018-10-25	71.630 mi
Registration #9	2018-10-26	71.692 mi
Registration #10	2019-08-09	80.349 mi
Registration #11	2019-08-09	80.349 mi
Registration #12	2019-08-09	80.349 mi
Registration #13	2019-08-09	80.349 mi
Registration #14	2019-08-09	80.349 mi
Registration #15	2019-08-09	80.349 mi
Registration #16	2019-08-09	80.349 mi
Registration #17	2019-08-09	80.349 mi
Registration #18	2019-08-09	80.349 mi
Registration #19	2019-08-09	80.349 mi
Registration #20	2019-08-09	80.349 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1890 mm
Height	1760 mm
Length	4660 mm
Wheel base	2700 mm
Kerb weight	1920 kg
Max. allowed weight	2570 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number	D4HBBU548086
---------------	--------------