



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	B-CLASS B180 CDI SE
Colour	Silver
Year of manufacture	2006
Top speed	114 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	250 Nm at 2.600 rpm
Engine capacity	1.992 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	50.4 mpg
CO2 emission	151 g/km
CO2 label	G





MOT history

MOT expiry date	2022-02-01
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	22
Total items failed	4

MOT #15 2021-02-02 10:59

MOT test number 536045907658

Result ✓ Passed

Next expiry date 2022-02-01

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #14 2019-05-30 09:33

MOT test number 127227106127

Result ✓ Passed

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Child Seat fitted not allowing full inspection of adult belt

**MOT #13** 2018-05-22 09:23**MOT test number** 918409176287**Result** ✓ Passed**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Central Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #12** 2017-05-10 12:11**MOT test number** 752842410593**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #11** 2017-05-10 09:37**MOT test number** 777149609479**Result** ✗ Failed**Fail** Offside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #10** 2016-05-31 10:35**MOT test number** 789995038176**Result** ✓ Passed**MOT #9** 2015-06-02 09:28**MOT test number** 367663555172**Result** ✓ Passed

**MOT #8** 2014-05-28 10:56**MOT test number** 215268644136**Result** ✓ Passed**MOT #7** 2013-05-30 13:19**MOT test number** 726800453171**Result** ✓ Passed**MOT #6** 2012-06-07 16:37**MOT test number** 127499352183**Result** ✓ Passed**MOT #5** 2012-06-07 16:37**MOT test number** 816789852194**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp not working on dipped beam (1.7.5a)**MOT #4** 2011-08-02 16:03**MOT test number** 558974211279**Result** ✓ Passed**MOT #3** 2010-08-19 09:56**MOT test number** 961311630231**Result** ✓ Passed**Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2010-08-19 09:39
MOT test number	404091630205
Result	✗ Failed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Fail	Offside Front Headlamp aim beam image kick up to the offside (1.8)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #1	2009-08-25 16:42
MOT test number	791257939211
Result	✓ Passed



Tax & MOT check

×

Untaxed

Tax expired:
17 February 2021

×

MOT

Expired:
1 February 2022

Tax status

Expired at 17 February 2021

Days left

1167 days too late

MOT expiry date

1 February 2022

Full MOT history

[See MOT history](#)

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	RK56ZBG
Plate since	2019-06-29
Current registration	RK56ZBG
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2006-09-12
Last registration	2021-02-02
Complete history	See info



Registration #1	2006-09-12	29 mi
Registration #2	2009-08-25	22.289 mi
Registration #3	2010-08-19	29.417 mi
Registration #4	2010-08-19	29.417 mi
Registration #5	2011-08-02	34.758 mi
Registration #6	2012-06-07	38.906 mi
Registration #7	2013-05-30	48.965 mi
Registration #8	2014-05-28	58.362 mi
Registration #9	2015-05-28	68.362 mi
Registration #10	2016-05-28	78.362 mi
Registration #11	2017-05-28	88.362 mi
Registration #12	2018-05-28	98.362 mi
Registration #13	2019-05-28	108.362 mi
Registration #14	2020-05-28	118.362 mi
Registration #15	2021-05-28	128.362 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1435 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	64094030249648