



TOYOTA



MM6IBPO


report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV-4 D-4D XT-R AWD
Colour	Grey
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	340 Nm at 2.800 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-11-26
Pictures	6
Listing price	View report



source: cargurus.co.uk





MOT history

MOT expiry date	2024-12-17
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	21
Total items failed	4

MOT #132023-12-05 09:59

MOT test number848121631527

Result✓ Passed

Next expiry date2024-12-17

- Advice

Nearside Rear Upper Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Offside Rear Tyre slightly damaged/cracking or perishing cracking in side walls (5.2.3 (d) (ii))
- Advice

Rear Oil leak, but not excessive nearside and offside output seals of the differential leaking (8.4.1 (a) (i))
- Advice

Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice

Fuel filler pipe corroded
- Advice

Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice

Offside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice

Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Nearside Rear Tyre slightly damaged/cracking or perishing cracking in side walls (5.2.3 (d) (ii))
- Advice

Offside Rear Upper Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice

Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice

Nearside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**MOT #12** 2022-11-28 11:36**MOT test number** 190519463884**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #11** 2021-11-29 15:58**MOT test number** 165732419389**Result** ✓ Passed**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #10** 2021-11-29 12:23**MOT test number** 427373683407**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #9** 2020-11-18 13:48**MOT test number** 387299441052**Result** ✓ Passed**MOT #8** 2019-11-25 09:31**MOT test number** 478210915520**Result** ✓ Passed

**MOT #7** 2019-11-25 09:31**MOT test number** 413991356085**Result** ✗ Failed

Pass with rectification Nearside Front Position lamp with a multiple light source more than 1/2 not functioning (4.2.1 (a) (ii))

MOT #6 2018-11-21 09:50**MOT test number** 293760799411**Result** ✓ Passed**MOT #5** 2017-11-22 11:05**MOT test number** 614734364325**Result** ✓ Passed**MOT #4** 2016-12-02 15:05**MOT test number** 213063946239**Result** ✓ Passed

Advice Front brake disc modified but not seriously weakened heavily lipped (3.5.1n)

MOT #3 2016-12-02 10:04**MOT test number** 388733785569**Result** ✗ Failed

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Front brake disc modified but not seriously weakened heavily lipped (3.5.1n)

MOT #2 2015-12-08 13:40**MOT test number** 515035958463**Result** ✓ Passed



MOT #1	2014-12-18 12:59
MOT test number	788762254320
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
17 December 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	17 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-02-09
Last registration	2023-12-05
Complete history	See info



Registration #1	2012-02-09	14 mi
Registration #2	2014-12-18	27.028 mi
Registration #3	2015-12-08	36.050 mi
Registration #4	2016-12-02	47.585 mi
Registration #5	2016-12-02	47.586 mi
Registration #6	2017-11-22	58.225 mi
Registration #7	2018-11-21	69.359 mi
Registration #8	2019-11-25	79.742 mi
Registration #9	2020-05-20	91.277 mi
Registration #10	2020-05-20	91.277 mi
Registration #11	2020-05-20	91.277 mi
Registration #12	2020-05-20	91.277 mi
Registration #13	2020-05-20	91.277 mi
Registration #14	2020-05-20	91.277 mi
Registration #15	2020-05-20	91.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1815 mm
Height	1685 mm
Length	4365 mm
Wheel base	2560 mm
Kerb weight	1650 kg
Max. allowed weight	2190 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	2AD0395056
---------------	------------