



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 1700 CDTI
Colour	Red
Year of manufacture	2007
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	170 Nm at 1.750 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-06
Pictures	4
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2021-11-21
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	22
Total items failed	1

MOT #12 2020-11-12 12:07

MOT test number 484027214923

Result ✓ Passed

Next expiry date 2021-11-21

- Advice** Front Play in steering rack inner joint(s) both
- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #11 2019-11-20 16:17

MOT test number 992073941213

Result ✓ Passed

- Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Play in steering rack inner joint(s) both
- Minor** Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #10** 2018-11-13 12:47**MOT test number** 256284523102**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Rear Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))**Advice** Play in steering rack inner joint(s)**MOT #9** 2017-11-18 10:06**MOT test number** 424980443109**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**MOT #8** 2016-11-22 13:49**MOT test number** 689833874545**Result** ✓ Passed**Advice** Nearside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)**MOT #7** 2015-05-28 14:45**MOT test number** 696878645177**Result** ✓ Passed**Notice** Brake & clutch pedal rubbers wearing**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #6** 2014-05-27 15:35**MOT test number** 756477144164**Result** ✓ Passed**MOT #5** 2014-05-21 10:11**MOT test number** 389561944146**Result** ✗ Failed**Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**MOT #4** 2013-06-12 09:54**MOT test number** 849583963155**Result** ✓ Passed**MOT #3** 2012-06-26 08:53**MOT test number** 208028372107**Result** ✓ Passed**MOT #2** 2011-07-01 15:52**MOT test number** 955312181166**Result** ✓ Passed**Notice** Off side front tyre 3mm**Notice** Deep cuts in tread of rear tyres**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Small hole in near side front outer cv boot**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #1** 2010-06-24 17:23**MOT test number** 270085970419**Result** ✓ Passed



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	WM07RBY
Plate since	2019-03-29
Current registration	WM07RBY
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2007-07-16
Last registration	2020-11-12
Complete history	See info



Registration #1	2007-07-16	7 mi
Registration #2	2010-06-24	64.992 mi
Registration #3	2011-07-01	85.332 mi
Registration #4	2012-06-26	101.096 mi
Registration #5	2013-06-12	115.636 mi
Registration #6	2014-05-21	131.443 mi
Registration #7	2014-05-27	161.443 mi
Registration #8	2015-05-20	181.277 mi
Registration #9	2016-05-20	191.277 mi
Registration #10	2017-05-20	201.277 mi
Registration #11	2018-05-20	211.277 mi
Registration #12	2019-05-20	221.277 mi
Registration #13	2020-05-20	231.277 mi
Registration #14	2021-05-20	241.277 mi

More info >



Dimensions & weight

Width	1892 mm
Height	1801 mm
Length	4323 mm
Kerb weight	1210 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	2163231