





report date: 2024-03-29

## General information

Make	MERCEDES
Model	CLK CLK240 ELEGANCE
Colour	Blue
Year of manufacture	2003
Top speed	143 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	170 BHP
Max. torque	240 Nm at 4.500 rpm
<b>Engine capacity</b>	2.597 cc
Cylinders	6
Fuel type	Petrol
Consumption city	18.8 mpg
Consumption extra urban	37.7 mpg
Consumption combined	28.0 mpg
CO2 emission	242 g/km
CO2 label	L



CarCheck.co.uk page 1/14



report date: 2024-03-29

# Internet history

## Entry 2

Date 2021-09-07

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

D	ate	2021-09-06

Pictures 42

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

# MOT history

MOT expiry date	2024-07-25
MOT pass rate	82 %
MOT passed	18
Failed MOT tests	4
Total advice items	21
Total items failed	6

MOT #22		2023-07-17 12:25
MOT test n	umber	132035885179
Result		✓ Passed
Next expir	y date	2024-07-25
Advice	Front Registration plate insecure but not likely to fall off (0.1 (a))	
Advice	Exhaust silencer slightly loose Heat Shield (8.1.1 (b) (i))	
Advice	Rear Registration plate insecure but not likely to fall off (0.1 (a))	
Advice	Rear Brake hose has slight corrosion to ferrule both side (1.1.12 (f) (i))	

MOT #21		2023-07-17 12:25
MOT test	number	807497831542
Result		<b>×</b> Failed
Advice	Front Registration plate insecure but not likely to fall off (0.1 (a))	
Advice	Exhaust silencer slightly loose Heat Shield (8.1.1 (b) (i))	
Pass wit	th rectification Nearside Headlamp aim too low (4.1.2 (a))	
Advice	Rear Registration plate insecure but not likely to fall off (0.1 (a))	
Advice	Rear Brake hose has slight corrosion to ferrule both side (1.1.12 (f) (i))	

CarCheck.co.uk page 3/14



report date: 2024-03-29

**MOT #20** 2022-07-26 12:18

**MOT test number** 990749329893

**MOT #19** 2022-07-19 15:42

**MOT test number** 324802146765

Result X Failed

Fail Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail Nearside Front Side repeater not working (4.4.1 (a) (ii))

MOT #18 2021-11-17 14:04

**MOT test number** 572109452265

**Result** ✓ Passed

**MOT #17** 2020-11-14 12:08

MOT test number 553576723489

**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #16** 2019-11-14 13:45

**MOT test number** 183385381017

**Advice** Exhaust silencer slightly loose (8.1.1 (b) (i))

Minor Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))

Minor Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #15	2018-11-01 15:02

MOT test number 335781178135

**Advice** Brake pipe corroded, covered in grease or other material n/s + o/s rear (1.1.11 (c))

**Advice** Coil spring corroded n/s + o/s front (5.3.1 (b) (i))

**MOT #14** 2017-11-02 15:00

MOT test number 686560819955

**Result** 
✓ Passed

MOT #13 2016-11-05 10:18

**MOT test number** 616565091315

Result \( \sqrt{Passed} \)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #12 2015-11-06 13:55

**MOT test number** 634302260046

Result \rightarrow Passed

**MOT #11** 2014-11-10 15:14

**MOT test number** 595214514398

MOT #10 2013-11-09 11:30

**MOT test number** 468303813301

**MOT #9** 2012-11-12 11:49

**MOT test number** 906377312389

**Result** 
✓ Passed

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #8 2011-11-04 16:32 MOT test number 245808901313

**Result** ✓ Passed

MOT #7 2011-11-04 11:08

**MOT test number** 396118001333

Result X Failed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT #6 2010-11-19 13:26

**MOT test number** 113853920352

Result \rightarrow Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2009-11-09 13:30

**MOT test number** 120653919383

**Result** ✓ Passed

**MOT #4** 2009-11-09 10:26

**MOT test number** 794043419335

Result X Failed

Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #3 2008-11-21 11:33

MOT test number 390316828383

**Result** ✓ Passed

**Notice** Child seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 6/14



MOT #2

DF53EHB report date: 2024-03-29

2007-10-25 11:32

MOT test number 330348797415

MOT #1 2007-02-27 13:51

MOT test number 700548257000

**Result** ✓ Passed

**Notice** CHILD SEAT FITTED TO BOTH REAR SEATS SO FULL INSPECTION OF BELTS NOT POSSIBLE, OFFSIDE FRONT SIDE REPEATER INSECURE, ADVISE REPLACE ALL FOUR TYRES SOON

CarCheck.co.uk page 7/14



DF53EHB report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	25 July 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

## Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

Date	
Category	
Туре	

#### Damage 2

Damage 2	
Date	
Category	



#### Extra MERCEDES salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

More info >

# Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downloaner.	
*********	
***************************************	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	IIK
Plate since	
Current registration	UK UK
Plate since	

CarCheck.co.uk page 11/14



report date: 2024-03-29

### Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

**Contact info** 

More info >


CarCheck.co.uk page 12/14



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2003-12-24
Last registration	2023-07-17
Complete history	See info



Registration #1	2003-12-24	6 mi
Registration #2	2007-02-27	26.460 mi
Registration #3	2007-10-25	31.053 mi
Registration #4	2008-11-21	36.966 mi
Registration #5	2009-11-09	42.654 mi
Registration #6	2009-11-09	42.654 mi
Registration #7	2010-11-19	49.092 mi
Registration #8	2011-11-04	56.060 mi
Registration #9	2011-11-04	56.060 mi
Registration #10	2012-11-12	62.880 mi
Registration #11	2013-11-09	70.765 mi
Registration #12	2014-11-10	75.542 mi
Registration #13	2015-11-06	77.725 mi
Registration #14		11.777 es
Registration #15		71.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		71.777 es
Registration #19		71.777 es
Registration #20		71.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		11.777 es
Registration #24		71.777 es
Registration #25		11.777 es



report date: 2024-03-29

# Dimensions & weight

Width	1740 mm
Height	1413 mm
Length	4643 mm
Wheel base	2690 mm
Kerb weight	1700 kg

## Additional information

Fuel tank capacity	62 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	11291231714836

CarCheck.co.uk page 14/14