



X998MFL

report date: 2024-03-28

General information

Make	HONDA
Model	HR-V
Colour	Grey
Year of manufacture	2000
Gearbox	-

Engine & fuel consumption

Engine capacity	1.600 cc
Fuel type	Petrol



LABEL UNKNOWN



MOT history

MOT expiry date	2021-02-19
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	28
Total items failed	5

MOT #17 2020-02-03 11:54

MOT test number 958593521366

Result ✓ Passed

Next expiry date 2021-02-19

- Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced offside and nearside chassis rails (6.1.1 (c) (i))
- Advice** Rear Lower Suspension rod pin or bush worn but not resulting in excessive movement offside and nearside (5.3.4 (a) (i))
- Advice** Front Lower Vehicle structure is corroded but structural rigidity is not significantly reduced offside and nearside floor pan sills (6.1.1 (c) (i))
- Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced offside and nearside inner sills (6.1.1 (c) (i))
- Advice** Offside Front driveshaft balancing weight deteriorated
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material above rear axle (1.1.11 (c))
- Advice** Nearside Rear Fuel Pipe/s corroded x2

**MOT #16**

2019-02-12 16:27

MOT test number

854160571603

Result

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced offside and nearside inner sills (6.1.1 (c) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material leading into wheel cylinder (1.1.11 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement offside and nearside (5.3.4 (a) (i))
- Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced offside and nearside chassis rails (6.1.1 (c) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material within wheel arch area (1.1.11 (c))

MOT #15

2018-02-09 17:08

MOT test number

583065086672

Result

✓ Passed

MOT #14

2018-02-02 11:05

MOT test number

853702529083

Result

✗ Failed

- Fail** Offside Stop lamp not working (1.2.1b)
- Fail** Central Rear Brake pipe excessively corroded (3.6.B.2c)
- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

**MOT #13** 2017-02-13 17:10**MOT test number** 334797942781**Result** ✓ Passed**Advice** Central Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #12** 2017-02-13 12:34**MOT test number** 263451869446**Result** ✗ Failed**Advice** Central Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Fail** Offside Rear Anti-roll bar has excessive play in a ball joint (2.4.G.2)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #11** 2016-02-10 17:33**MOT test number** 785990811727**Result** ✓ Passed**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Vehicle structure has slight corrosion (6.1.A.1)**Advice** Offside Rear coil spring corroded (2.4.C.1b)



MOT #10	2015-02-12 14:50
MOT test number	337203445067
Result	✓ Passed
Advice	Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
MOT #9	2014-02-14 15:21
MOT test number	146305644410
Result	✓ Passed
MOT #8	2013-02-15 13:02
MOT test number	417116843005
Result	✓ Passed
MOT #7	2012-02-17 12:14
MOT test number	569318542003
Result	✓ Passed
MOT #6	2011-02-08 11:35
MOT test number	345219531025
Result	✓ Passed
MOT #5	2010-02-15 16:14
MOT test number	503166440012
Result	✓ Passed
MOT #4	2009-02-18 17:05
MOT test number	760849149028
Result	✓ Passed



MOT #3	2008-02-07 15:00
MOT test number	561258538016
Result	✓ Passed
MOT #2	2007-02-16 10:41
MOT test number	451817547046
Result	✓ Passed
MOT #1	2006-02-20 18:42
MOT test number	172801356410
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
23 December 2020

✕
MOT

Expired:
19 February 2021

Tax status

Expired at 23 December 2020

Days left

1224 days too late

MOT expiry date

19 February 2021

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	X998MFL
Plate since	2024-03-28
Current registration	X998MFL
Plate since	2024-03-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2000-12-18
Last registration	2020-02-03
Complete history	See info



Registration #1	2000-12-18	7 mi
Registration #2	2006-02-20	63.336 mi
Registration #3	2007-02-16	68.205 mi
Registration #4	2008-02-07	70.735 mi
Registration #5	2009-02-18	73.410 mi
Registration #6	2010-02-15	76.166 mi
Registration #7	2011-02-08	78.861 mi
Registration #8	2012-02-17	81.819 mi
Registration #9	2013-02-15	84.400 mi
Registration #10	2014-02-15	85.337 mi
Registration #11	2015-02-15	85.337 mi
Registration #12	2016-02-15	85.337 mi
Registration #13	2017-02-15	85.337 mi
Registration #14	2018-02-15	85.337 mi
Registration #15	2019-02-15	85.337 mi
Registration #16	2020-02-03	85.337 mi
Registration #17	2020-02-03	85.337 mi
Registration #18	2020-02-03	85.337 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)



Additional information

Number of seats

4

Engine number

B16B