



RENAULT

MA06ZVE

report date: 2024-03-29

General information

Make	RENAULT
Model	ESPACE RUSH DCI (120BHP)
Colour	Blue
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	13.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	270 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	40.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-09
Pictures	16
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #16	2020-11-26 10:09
MOT test number	801087860268
Result	✓ Passed
Next expiry date	2021-12-07
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2019-06-08 10:28
MOT test number	746627917478
Result	✓ Passed
Advice	Central Front brake lamp not working
Minor	Offside Windscreen wiper blade defective (3.4 (b) (i))

MOT #14	2019-06-07 15:44
MOT test number	404531783463
Result	✗ Failed
Fail	Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Central Front brake lamp not working
Fail	Nearside Front Position lamp not working (4.2.1 (a))
Minor	Offside Windscreen wiper blade defective (3.4 (b) (i))

MOT #13	2018-05-18 14:00
MOT test number	172310740999
Result	✓ Passed

MOT #12	2017-06-02 10:11
MOT test number	483801316365
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit also has nail in tyre (4.1.E.1)
Advice	Nearside Rear Nail in tyre

**MOT #11** 2017-06-02 10:07**MOT test number** 577213293072**Result** ✗ Failed**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Nearside Front Tyre worn close to the legal limit on limit (4.1.E.1)**Advice** Nearside Rear Nail in tyre**Fail** Offside Front Tyre has ply or cords exposed inner edge (4.1.D.1b)**Advice** Offside Rear Tyre worn close to the legal limit also has nail in tyre (4.1.E.1)**MOT #10** 2017-06-01 11:47**MOT test number** 962289756347**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed inner edge (4.1.D.1b)**Advice** Offside Rear Tyre worn close to the legal limit also has nail in tyre (4.1.E.1)**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Nearside Front Tyre worn close to the legal limit on limit (4.1.E.1)**Advice** Nearside Rear Nail in tyre**MOT #9** 2016-06-02 09:46**MOT test number** 796140451478**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit on limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #8** 2015-06-05 10:48**MOT test number** 596606355133**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2014-05-28 09:54**MOT test number** 177998044122**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2013-06-06 16:21**MOT test number** 296137153128**Result** ✓ Passed**Notice** Oil leak**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Crack in front number plate.**Notice** Under-trays fitted obscuring some underside components**Notice** Items removed from driver's view prior to test**Notice** Front wipers showing signs of wear.

**MOT #5** 2013-06-04 16:42**MOT test number** 228715053456**Result** ✗ Failed

- Notice** Items removed from driver's view prior to test
- Notice** Front wipers showing signs of wear.
- Notice** Oil leak
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Crack in front number plate.
- Fail** Steering lock inadvertently engaging (2.1.4a)
- Notice** Under-trays fitted obscuring some underside components

MOT #4 2012-06-01 15:34**MOT test number** 148213652187**Result** ✓ Passed**MOT #3** 2011-06-08 09:08**MOT test number** 199649351142**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Front number plate cracked
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2010-10-06 12:13**MOT test number** 804009370289**Result** ✓ Passed



MOT #1	2009-03-26 11:23
MOT test number	431215589066
Result	✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-03-29
Last registration	2020-11-26
Complete history	See info



Registration #1	2006-03-29	6 mi
Registration #2	2009-03-26	32.013 mi
Registration #3	2010-10-06	49.209 mi
Registration #4	2011-06-08	52.921 mi
Registration #5	2012-06-01	57.672 mi
Registration #6	2013-06-04	63.463 mi
Registration #7	2013-06-06	63.463 mi
Registration #8	2014-05-28	69.124 mi
Registration #9	2015-06-05	75.517 mi
Registration #10	2016-06-05	81.910 mi
Registration #11	2017-06-05	88.303 mi
Registration #12	2018-06-05	94.696 mi
Registration #13	2019-06-05	101.089 mi
Registration #14	2020-06-05	107.482 mi
Registration #15	2021-06-05	113.875 mi
Registration #16	2022-06-05	120.268 mi
Registration #17	2023-06-05	126.661 mi
Registration #18	2024-06-05	133.054 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2104 mm
Height	1782 mm
Length	4661 mm
Wheel base	2803 mm
Kerb weight	1755 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	83 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	C041544