



report date: 2024-03-29

General information

Make	VOLVO
Model	S40 E4 D SE SPORT S40
Colour	Silver
Year of manufacture	2006
Top speed	130 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	148 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-08-28
Pictures	18
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2025-05-11
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	23
Total items failed	3

MOT #16	2024-04-24 08:26
MOT test number	817754329981
Result	✓ Passed
Next expiry date	2025-05-11
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #15	2023-04-27 09:15
MOT test number	232219136654
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Worn low on edges (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge Worn low on inner edge (5.2.3 (e))
Advice	Parking brake lever travel only just acceptable - advise adjustment/repair

MOT #14	2022-05-12 09:00
MOT test number	775603924492
Result	✓ Passed

**MOT #13** 2021-05-01 10:53**MOT test number** 668592374345**Result** ✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush (5.3.4 (a) (i))

Advice Offside Front Road wheel slightly distorted Inner rim (5.2.2 (c) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush (5.3.4 (a) (i))

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #12 2019-03-24 13:57**MOT test number** 414280583083**Result** ✓ Passed**MOT #11** 2019-03-24 13:57**MOT test number** 390551607387**Result** ✗ Failed

Pass with rectification Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #10 2017-01-30 10:40**MOT test number** 389388613371**Result** ✓ Passed**MOT #9** 2016-02-17 12:55**MOT test number** 515376824632**Result** ✓ Passed

**MOT #8** 2015-02-19 10:16**MOT test number** 775790755042**Result** ✓ Passed**Advice** Offside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Nsr tyre has sidewall damage but not to cords**Notice** Under-trays fitted obscuring some underside components**Notice** Emissions too clean for smoke machine**MOT #7** 2015-02-19 10:16**MOT test number** 667900955087**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Notice** Emissions too clean for smoke machine**Advice** Offside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**Notice** Engine covers fitted obscuring some components in the engine bay**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Notice** Nsr tyre has sidewall damage but not to cords**MOT #6** 2014-02-19 16:12**MOT test number** 167210654440**Result** ✓ Passed

**MOT #5** 2013-02-15 14:38**MOT test number** 638186143079**Result** ✓ Passed**Notice** N/s/f and n/s/r - outer sidewalls - damaged (no cords or structure exposed)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #4** 2012-02-21 14:01**MOT test number** 315022852000**Result** ✓ Passed**MOT #3** 2011-02-21 16:22**MOT test number** 165582651494**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #2** 2010-03-08 13:54**MOT test number** 863017960066**Result** ✓ Passed**MOT #1** 2009-03-12 15:00**MOT test number** 770611079006**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
11 May 2025

Tax status	Valid until 1 June
Days left	32
MOT expiry date	11 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2006-03-31
Last registration	2024-04-24
Complete history	See info



Registration #1	2006-03-31	13 mi
Registration #2	2009-03-12	15.667 mi
Registration #3	2010-03-08	17.917 mi
Registration #4	2011-02-21	20.814 mi
Registration #5	2012-02-21	23.608 mi
Registration #6	2013-02-15	29.408 mi
Registration #7	2014-02-19	36.874 mi
Registration #8	2015-02-19	44.462 mi
Registration #9	2016-02-17	52.316 mi
Registration #10	2016-03-29	55.377 mi
Registration #11	2016-03-29	55.377 mi
Registration #12	2016-03-29	55.377 mi
Registration #13	2016-03-29	55.377 mi
Registration #14	2016-03-29	55.377 mi
Registration #15	2016-03-29	55.377 mi
Registration #16	2016-03-29	55.377 mi
Registration #17	2016-03-29	55.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4468 mm
Wheel base	2640 mm
Kerb weight	1426 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	4013441