



report date: 2024-03-29

General information

Make	MINI
Model	COOPER S
Colour	Black
Year of manufacture	-
Top speed	142 mph
0 - 60 mph	7.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	48.7 mpg



LABEL UNKNOWN

**MOT history**

MOT #11	2020-08-20 15:49
MOT test number	533808445194
Result	✓ Passed
Next expiry date	2021-08-19

MOT #10	2020-08-20 15:49
MOT test number	744178637249
Result	✗ Failed

Pass with rectification Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #9	2019-06-06 11:46
MOT test number	606818645587
Result	✓ Passed

MOT #8	2018-10-29 12:41
MOT test number	926099718335
Result	✓ Passed

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #7	2018-10-29 09:24
MOT test number	427237822203
Result	✗ Failed

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #6	2017-10-30 16:53
MOT test number	457565705365
Result	✓ Passed

Advice Nearside Front Tyre worn close to the legal limit on 3mm (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit on 3mm (4.1.E.1)

**MOT #5** 2017-10-30 10:13**MOT test number** 767342598168**Result** ✗ Failed**Fail** Brake fluid warning lamp illuminated (3.6.G.2)**Advice** Nearside Front Tyre worn close to the legal limit on 3mm (4.1.E.1)**Advice** Brake pads low warning message on dash**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Rear Tyre worn close to the legal limit on 3mm (4.1.E.1)**MOT #4** 2016-10-28 08:28**MOT test number** 126674896669**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both corroded (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both corroded (3.5.1i)**MOT #3** 2015-10-23 11:07**MOT test number** 970150182207**Result** ✓ Passed**MOT #2** 2015-09-16 08:38**MOT test number** 916814033328**Result** ✓ Passed**MOT #1** 2015-05-29 14:36**MOT test number** 847649445113**Result** ✓ Passed



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-05-31
Last registration	2020-08-20
Complete history	See info



Registration #1	2012-05-31	29 mi
Registration #2	2015-05-29	20.350 mi
Registration #3	2015-09-16	21.768 mi
Registration #4	2015-10-23	21.784 mi
Registration #5	2016-10-28	35.204 mi
Registration #6	2017-10-30	42.270 mi
Registration #7	2019-05-20	55.277 mi
Registration #8	2019-05-20	55.277 mi
Registration #9	2019-05-20	55.277 mi
Registration #10	2019-05-20	55.277 mi
Registration #11	2019-05-20	55.277 mi
Registration #12	2019-05-20	55.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3714 mm
Wheel base	2467 mm
Kerb weight	1130 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	A631J326