





report date: 2024-03-28

# General information

Make	HYUNDAI
Model	IX35 GDI S
Colour	Silver
Year of manufacture	2014
Top speed	111 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	133 BHP
Max. torque	165 Nm at 4.850 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	47.1 mpg
Consumption combined	41.5 mpg
CO2 emission	158 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-28

# Internet history

## Entry 1


Date 2021-07-04


Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-06-28
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	12
Total items failed	1

MOT #9	2023-06-29 16:19
MOT test number	839381519425
Result	<b>✓</b> Passed
Next expiry date	2024-06-28

MOT #8	2023-06-27 12:18
MOT test number	699761190282
Result	<b>X</b> Failed
Advice Brake disc worn, pitted or scored, but not seriously weakened BOTH REAR	(1.1.14 (a) (ii))
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	

MOT #7	2022-06-28 13:16
MOT test number	393798549432
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

**MOT** #6 2022-06-28 09:56 **MOT** test number 418887378819 ✓ Passed Result Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) FRONT EXHAUST FLEXI CORRODED **Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f)) **Advice** Minor Nearside Front Obligatory mirror slightly loose (3.3 (b) (i)) **Advice** Tyre worn close to legal limit/worn on edge BOTH FRONT (5.2.3 (e))

 MOT #5
 2021-07-02 12:34

 MOT test number
 729543468552

 Result
 ✓ Passed

MOT test number

123026880413

Result

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT test number

Result

Advice
Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice
Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #2	2018-08-20 10:24
MOT test number	894605206477
Result	<b>✓</b> Passed
MOT #1	2017-08-31 09:54
MOT test number	420319880988

CarCheck.co.uk page 5/12



report date: 2024-03-28

# Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	28 June 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

## Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



EO14BBZ report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



faste since

EO14BBZ

report date: 2024-03-28

More info >

# Owner history For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this HYUNDAI had different number plates. about of pliates

CarCheck.co.uk page 9/12



EO14BBZ report date: 2024-03-28

## Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-08-29
Last registration	2023-06-29
Complete history	See info



Registration #1	2014-08-29	17 mi
Registration #2	2017-08-31	35.765 mi
Registration #3	2018-08-20	45.066 mi
Registration #4	2019-09-03	57.983 mi
Registration #5	2020-09-08	62.817 mi
Registration #6	2021-07-02	67.162 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		71.777 mg

More info >

CarCheck.co.uk page 11/12



EO14BBZ report date: 2024-03-28

Car features

S0225	Air conditionin
50295	
50482	
50501	
60566	
60567	
50569	

# Safety ratings

NCAP rating	****
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



# Dimensions & weight

Width	1820 mm
Height	1655 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1427 kg
Max. allowed weight	1830 kg

## Additional information

Fuel tank capacity	58 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/1.

Number of axles 2

**Engine number** G4FDEZ867300