



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE TOMTOM EDITION DCI
Colour	Grey
Year of manufacture	2009
Top speed	108 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	86 BHP
Max. torque	200 Nm at 1.900 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	70.6 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	C





Internet history

Entry 3

Date 2021-08-30

Pictures 10

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 2

Date 2021-07-30

Pictures 10

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date 2021-07-01

Pictures 10

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-30
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	25
Total items failed	12

MOT #17 2023-12-01 14:27

MOT test number 264835097091

Result ✓ Passed

Next expiry date 2024-11-30

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Parking brake just met minimum requirement to pass needs to be looked at

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #16 2023-12-01 12:10

MOT test number 722602093801

Result ✗ Failed

Advice Parking brake just met minimum requirement to pass needs to be looked at

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #15 2022-11-02 09:19

MOT test number 211286187392

Result ✓ Passed

**MOT #14** 2022-11-01 12:10**MOT test number** 747557539112**Result** ✗ Failed**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Rear Inner Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Nearside Rear Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))**MOT #13** 2021-10-30 11:23**MOT test number** 195757924793**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**MOT #12** 2021-10-30 09:54**MOT test number** 756392998167**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**MOT #11** 2020-10-27 14:34**MOT test number** 630148519478**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened all (1.1.14 (a) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Tyre worn close to legal limit/worn on edge all (5.2.3 (e))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #10**

2020-10-27 09:49

MOT test number

544141994355

Result**✗ Failed****Advice** Brake disc worn, pitted or scored, but not seriously weakened all (1.1.14 (a) (ii))**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Tyre worn close to legal limit/worn on edge all (5.2.3 (e))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #9**

2019-10-30 13:32

MOT test number

890889880682

Result**✓ Passed****MOT #8**

2019-10-30 13:32

MOT test number

706431100046

Result**✗ Failed****Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**MOT #7**

2018-10-31 11:14

MOT test number

442727257402

Result**✓ Passed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6** 2017-10-25 10:11**MOT test number** 807358341898**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Brake disc worn, pitted or scored, but not seriously weakened all (3.5.1i)**MOT #5** 2016-10-28 11:36**MOT test number** 652626146303**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened all (3.5.1i)**MOT #4** 2015-10-29 13:23**MOT test number** 350056460078**Result** ✓ Passed**MOT #3** 2014-10-24 17:42**MOT test number** 368167694455**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #2** 2013-10-29 12:04**MOT test number** 616232203333**Result** ✓ Passed



MOT #1	2012-10-06 12:17
MOT test number	558890282205
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
30 November 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	30 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-11-01
Last registration	2023-12-01
Complete history	See info



Registration #1	2009-11-01	25 mi
Registration #2	2012-10-06	48.292 mi
Registration #3	2013-10-29	59.196 mi
Registration #4	2014-10-24	75.197 mi
Registration #5	2015-10-29	83.842 mi
Registration #6	2016-10-28	89.051 mi
Registration #7	2017-10-25	99.030 mi
Registration #8	2018-10-31	106.354 mi
Registration #9	2019-10-30	112.577 mi
Registration #10	2019-10-30	112.577 mi
Registration #11	2020-10-27	116.509 mi
Registration #12	2020-10-27	116.509 mi
Registration #13	2020-10-27	116.509 mi
Registration #14	2020-10-27	116.509 mi
Registration #15	2020-10-27	116.509 mi
Registration #16	2020-10-27	116.509 mi
Registration #17	2020-10-27	116.509 mi
Registration #18	2020-10-27	116.509 mi
Registration #19	2020-10-27	116.509 mi
Registration #20	2020-10-27	116.509 mi
Registration #21	2020-10-27	116.509 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1720 mm
Height	1497 mm
Length	4032 mm
Wheel base	2575 mm
Kerb weight	1175 kg
Max. allowed weight	1665 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D390561