





report date: 2024-03-28

#### General information

Make	FIAT
Model	PANDA POP
Colour	Black
Year of manufacture	2015
Top speed	99 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/11



### Internet history

#### Entry 2

Date 2021-07-25

Pictures 3

Listing price <u>View report</u>







source: yesauto.com

#### Entry 1

Date	2021-07-23
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-09-30
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	9
Total items failed	0

MOT #10	2023-09-07 11:06
MOT test number	732280830476
Result	<b>✓</b> Passed
Next expiry date	2024-09-30

MOT #9		2023-09-06 08:10
MOT test	number	457391534742
Result		<b>×</b> Failed
MAJOR	Offside Front Position lamp not working (4.2.1 (a) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii	i))

MOT #8	2022-09-12 12:27
MOT test number	583812481518
Result	<b>✓</b> Passed
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #7	2021-10-01 08:14
MOT test number	114644302407
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/11



MOT #6 2021-04-01 11:50

**MOT test number** 555655479025

**Result** ✓ Passed

MOT #5 2021-03-23 16:14

**MOT test number** 123491657851

Result X Failed

**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**Advice** Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))

MOT #4 2020-03-25 16:25

**MOT test number** 134683070567

Result \( \sqrt{Passed} \)

MOT #3 2020-03-24 15:48

MOT test number 432393354567

Result X Failed

MAJOR Nearside Front Obligatory mirror insecure (3.3 (b) (ii))

MOT #2 2019-03-15 09:31

MOT test number 430735284653

**Result** ✓ Passed

MOT #1 2018-03-17 09:33

MOT test number 419125124740

Result 

Passed

**Advice** Nearside Front Tyre worn to inner edge of tread

CarCheck.co.uk page 4/11





#### Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	30 September 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



## Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
HARMAN CO.	
***************************************	
*********	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	NIE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



## Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-03-28
Last registration	2023-09-07
Complete history	See info



Registration #1	2015-03-28	29 mi
Registration #2	2018-03-17	12.693 mi
Registration #3	2019-03-15	13.967 mi
Registration #4	2020-03-24	15.519 mi
Registration #5	2020-03-25	15.519 mi
Registration #6	2021-03-23	21.214 mi
Registration #7	2021-04-01	21.225 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 es
Registration #12		11.777 es
Registration #13		70.777 au

More info >

CarCheck.co.uk page 10/11



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	82%
Children	63%
Pedestrian	49%
Safety systems	43%
Overall rating	68%
Video	see crash video



# Dimensions & weight

Width	1643 mm
Height	1551 mm
Length	3653 mm
Wheel base	2300 mm
Kerb weight	1015 kg
Max. allowed weight	1420 kg

## Additional information

Fuel tank capacity	37
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 11/11

Number of axles 2
Engine number 1121042