



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	I800 CRDI STYLE
Colour	Silver
Year of manufacture	2012
Top speed	112 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	168 BHP
Max. torque	440 Nm at 2.500 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.1 mpg
CO2 emission	231 g/km
CO2 label	L






Internet history

Entry 2

Date 2022-01-29

Pictures 9



Listing price [View report](#)

source: cargurus.co.uk

Entry 1

Date 2022-01-28

Pictures 9

Listing price [View report](#)

source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-29
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	42
Total items failed	14

MOT #14	2023-08-25 15:00
MOT test number	724215294178
Result	✓ Passed
Next expiry date	2024-08-29
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #13	2022-08-30 12:51
MOT test number	389054571169
Result	✓ Passed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
Minor	Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #12	2022-08-27 11:43
MOT test number	570102881877
Result	✗ Failed
Advice	Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Minor	Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #11**

2021-08-25 07:49

MOT test number

867492595517

Result

✓ Passed

- Advice** Front Seat belt webbing slightly damaged or frayed both seat (7.1.2 (b) (ii))
- Advice** Central Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #10

2021-08-18 15:31

MOT test number

353071475326

Result

✗ Failed

- Advice** Front Seat belt webbing slightly damaged or frayed both seat (7.1.2 (b) (ii))
- Fail** Nearside Front Headlamp aim too high (4.1.2 (a))
- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Central Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
- Fail** Offside Front Headlamp aim too high (4.1.2 (a))

**MOT #9** 2020-08-24 15:14**MOT test number** 494035656107**Result** ✓ Passed**Advice** Brake pad(s) wearing thin both fronts (1.1.13 (a) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Minor** Other passenger door catch deteriorated so the door cannot be readily opened or closed nsr door (6.2.3 (c) (i))**Advice** Brake disc worn, pitted or scored, but not seriously weakened both fronts (1.1.14 (a) (ii))**Minor** Nearside Front Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #8** 2019-08-27 14:42**MOT test number** 219612653696**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Inner Tyre slightly damaged/cracking or perishing Tread wear (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing wear on inner and outer tread (5.2.3 (d) (ii))

**MOT #7**

2019-08-14 13:48

MOT test number

281756571068

Result**✗ Failed**

- Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))
- Advice** Offside Front Inner Tyre slightly damaged/cracking or perishing Tread wear (5.2.3 (d) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Fail** Offside Parking brake inoperative on one side (1.4.1 (a))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing wear on inner and outer tread (5.2.3 (d) (ii))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps Both lights not working (4.7.1 (b) (ii))

MOT #6

2018-08-15 10:45

MOT test number

852455707661

Result**✓ Passed**

- Advice** Rear Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))
- Advice** Front Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))

MOT #5

2018-08-15 10:45

MOT test number

121586136649

Result**✗ Failed**

- Advice** Front Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))
- Advice** Rear Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))

**MOT #4**

2017-08-18 13:22

MOT test number

102671022115

Result

✓ Passed

Advice

Both front tyres worn on inner edges

Advice

Child Seat fitted not allowing full inspection of adult belt middle row nearside and offside

Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3

2016-07-21 11:26

MOT test number

248185210881

Result

✓ Passed

Advice

Middle row seats unable to check inner and outer seatbelts , child seats fitted

Advice

Brake hydraulic reservoir fluid close to minimum level brake master cylinder (3.6.G.1b)

MOT #2

2016-07-18 10:48

MOT test number

322594739828

Result

✗ Failed

Advice

Brake hydraulic reservoir fluid close to minimum level brake master cylinder (3.6.G.1b)

Fail

Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail

Nearside Front Headlamp aim beam image obviously incorrect dazzling and high (1.8.A.1b)

Fail

Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail

Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail

Offside Front Headlamp aim too low (1.8)

Fail

Offside Rear Registration plate lamp not working (1.1.C.1d)

Advice

Middle row seats unable to check inner and outer seatbelts , child seats fitted



MOT #1	2015-06-12 15:43
MOT test number	689193665162
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Both front tyres wearing on inner edge



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-06-01
Last registration	2023-08-25
Complete history	See info



Registration #1	2012-06-01	19 mi
Registration #2	2015-06-12	50.511 mi
Registration #3	2016-07-18	64.888 mi
Registration #4	2016-07-21	64.975 mi
Registration #5	2017-08-18	77.910 mi
Registration #6	2018-08-15	88.905 mi
Registration #7	2018-08-15	88.905 mi
Registration #8	2019-08-14	104.456 mi
Registration #9	2019-08-27	104.946 mi
Registration #10	2019-08-27	104.946 mi
Registration #11	2019-08-27	104.946 mi
Registration #12	2019-08-27	104.946 mi
Registration #13	2019-08-27	104.946 mi
Registration #14	2019-08-27	104.946 mi
Registration #15	2019-08-27	104.946 mi
Registration #16	2019-08-27	104.946 mi
Registration #17	2019-08-27	104.946 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5125 mm
Wheel base	3200 mm
Kerb weight	2270 kg
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8

Engine number	D4CBC995094
---------------	-------------