





report date: 2024-03-29

#### General information

Make	BMW
Model	316 118I M SPORT
Colour	White
Year of manufacture	2013
Top speed	140 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	168 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	47.9 mpg
CO2 emission	137 g/km
CO2 label	E



CarCheck.co.uk page 1/11



report date: 2024-03-29

## Internet history

## Entry 2

Date 2021-07-16

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2021-07-14

Pictures 62

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

## MOT history

MOT expiry date	2024-06-30
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	12
Total items failed	4

MOT #10	2023-07-01 10:49
MOT test number	118881773255
Result	<b>✓</b> Passed
Next expiry date	2024-06-30
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Brake disc worn, pitted or scored, but not seriously weakened all four brake discs scored and worn (1.1.14 (a) (ii))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #9	2022-03-31 11:21
MOT test number	905441828838
Result	✓ Passed
Advice Exhaust emits blue smoke during acceleration (8.2.1.2 (g))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #8 2022-03-30 09:15 **MOT test number** 840947041560 Result **X** Failed **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Nearside Side repeater not working (4.4.1 (a) (ii)) Fail Fail Offside Windscreen washer not working (3.5 (a)) Advice Nearside Front Nail in tyre Nearside Windscreen washer not working (3.5 (a)) Fail Advice Exhaust emits blue smoke during acceleration (8.2.1.2 (g))

MOT #7	2021-11-03 17:48
MOT test number	339622957464
Result	✓ Passed
MOT #6	2020-10-17 09:12
MOT test number	272753431996
Result	✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Rear Nail in tyre	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #5	2019-10-19 08:57
MOT test number	707091819792
Result	<b>✓</b> Passed
MOT #4	2018-10-24 12:52
MOT test number	150990023636
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

 MOT #3
 2018-01-11 12:37

 MOT test number
 512757971576

 Result
 ✓ Passed

 MOT #2
 2016-11-03 13:13

 MOT test number
 482765383723

 Result
 ✓ Passed

 Advice
 Offside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #1

MOT test number

Result

Pass with rectification

Nearside Front Headlamp aim too low (1.8)

Advice

Offside Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

## Owner history

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report	
*********	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	NK SIK
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-12-27
Last registration	2023-07-01
Complete history	See info



Registration #1	2013-12-27	26 mi
Registration #2	2016-11-03	64.491 mi
Registration #3	2016-11-03	64.491 mi
Registration #4	2018-01-11	80.514 mi
Registration #5	2018-10-24	83.068 mi
Registration #6	2019-10-19	95.914 mi
Registration #7	2020-10-17	107.645 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		0.00 44
Registration #11		11.777 mi
Registration #12		0.00 44
Registration #13		0.00 44

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
50569	

# Safety ratings

NCAP rating	****
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	1765 mm
Height	1421 mm
Length	4324 mm
Wheel base	2690 mm
Kerb weight	1300 kg
Max. allowed weight	1865 kg

## Additional information

Fuel tank capacity	52 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 11/1:

Number of axles2Engine numberA172J594