



SP09ZPM

report date: 2024-03-29

General information

Make	FORD
Model	FOCUS ZETEC
Colour	Silver
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	143 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.9 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-05-27
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-09-24
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	35
Total items failed	16

## MOT #18 2023-09-13 12:28

MOT test number 358300066728

Result ✓ Passed

Next expiry date 2024-09-24

**Advice** Offside Front Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Front and rear suspension corroded**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**Advice** N/s/f o/s/f wing corroded

## MOT #17 2022-09-20 10:35

MOT test number 947128530373

Result ✓ Passed**Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced under vehicle (6.1.1 (c) (i))

## MOT #16 2021-09-25 11:08

MOT test number 937277151024

Result ✓ Passed

**MOT #15**

2020-08-12 15:17

**MOT test number**

359297859890

**Result**

✓ Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rearmost (5.3.4 (a) (i))

**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rearmost (5.3.4 (a) (i))

**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**MOT #14**

2020-08-11 14:52

**MOT test number**

447346812920

**Result**

✗ Failed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rearmost (5.3.4 (a) (i))

**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**Fail** Nearside Stop lamp(s) light intensity significantly reduced (4.3.3 (a) (ii))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rearmost (5.3.4 (a) (i))

**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))

**Fail** Offside Stop lamp(s) light intensity significantly reduced (4.3.3 (a) (ii))

**MOT #13**

2019-08-07 09:48

**MOT test number**

845551008158

**Result**

✓ Passed

**MOT #12**

2019-08-07 09:48

**MOT test number**

448162100174

**Result****✗ Failed**

- Pass with rectification** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Pass with rectification** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Pass with rectification** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Pass with rectification** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #11**

2018-08-08 07:43

**MOT test number**

941576608772

**Result****✓ Passed**

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** All tyres worn on inside
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened inside discs (1.1.14 (a) (ii))

**MOT #10**

2017-08-11 08:34

**MOT test number**

973349086388

**Result****✓ Passed**

- Advice** Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Suspension arm has slight play in a pin/bush rear bush (2.4.G.2)
- Advice** Offside Rear Tyre worn close to the legal limit uneven wear. (4.1.E.1)
- Advice** Nearside Front Suspension arm has slight play in a pin/bush rear bush (2.4.G.2)
- Advice** Nearside Rear Tyre worn close to the legal limit uneven wear. (4.1.E.1)

**MOT #9** 2017-08-10 10:03**MOT test number** 339590010778**Result** ✗ Failed

- Fail** Offside Rear Brake cable has restricted free movement (3.5.1k)
- Fail** Nearside Rear Anti-roll bar attachment bracket/mounting fractured (2.4.G.1)
- Advice** Nearside Front Suspension arm has slight play in a pin/bush rear bush (2.4.G.2)
- Advice** Nearside Rear Tyre worn close to the legal limit uneven wear. (4.1.E.1)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Offside Rear rear parking brake recording little or no effort (3.7.B.6a)
- Advice** Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Offside Rear Anti-roll bar attachment bracket/mounting fractured (2.4.G.1)
- Advice** Offside Front Suspension arm has slight play in a pin/bush rear bush (2.4.G.2)
- Advice** Offside Rear Tyre worn close to the legal limit uneven wear. (4.1.E.1)

**MOT #8** 2016-08-03 11:04**MOT test number** 490214592318**Result** ✓ Passed

- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Large interior mirror fitted and toys hanging but not obscuring drivers view.

**MOT #7** 2016-08-03 11:04**MOT test number** 598475396882**Result** ✗ Failed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Large interior mirror fitted and toys hanging but not obscuring drivers view.**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #6** 2015-08-05 10:06**MOT test number** 959287451482**Result** ✓ Passed**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)**MOT #5** 2014-08-12 11:29**MOT test number** 278114324202**Result** ✓ Passed**MOT #4** 2013-07-19 10:59**MOT test number** 155560103275**Result** ✓ Passed**MOT #3** 2012-08-01 14:05**MOT test number** 749694712201**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #2** 2012-02-24 16:25**MOT test number** 395845252094**Result** ✓ Passed



MOT #1	2012-02-24 16:25
MOT test number	996835452001
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
Pass with rectification	Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
24 September 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	24 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>SP09ZPM</b>
Plate since	2024-03-29
Current registration	<b>SP09ZPM</b>
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-04-09
Last registration	2023-09-13
Complete history	<a href="#">See info</a>



Registration #1	2009-04-09	10 mi
Registration #2	2012-02-24	30.275 mi
Registration #3	2012-08-01	33.016 mi
Registration #4	2013-07-19	40.055 mi
Registration #5	2014-08-12	47.894 mi
Registration #6	2015-08-05	54.239 mi
Registration #7	2016-08-03	59.509 mi
Registration #8	2016-08-03	59.509 mi
Registration #9	2017-08-10	64.744 mi
Registration #10	2017-08-11	64.746 mi
Registration #11	2018-08-03	69.777 mi
Registration #12	2018-08-03	69.777 mi
Registration #13	2018-08-03	69.777 mi
Registration #14	2018-08-03	69.777 mi
Registration #15	2018-08-03	69.777 mi
Registration #16	2018-08-03	69.777 mi
Registration #17	2018-08-03	69.777 mi
Registration #18	2018-08-03	69.777 mi
Registration #19	2018-08-03	69.777 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1998 mm
Height	1430 mm
Length	4152 mm
Wheel base	2640 mm
Kerb weight	1277 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	9U51607