



Mercedes-Benz



report date: 2024-03-28

General information

| | |
|---------------------|----------------------------------|
| Make | MERCEDES |
| Model | CLK CLK200 KOMPRESSOR AVANTGARDE |
| Colour | Silver |
| Year of manufacture | 2005 |
| Top speed | 139 mph |
| 0 - 60 mph | 10.5 seconds |
| Gearbox | 5 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 161 BHP |
| Max. torque | 240 Nm at 4.000 rpm |
| Engine capacity | 1.796 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 22.1 mpg |
| Consumption extra urban | 41.5 mpg |
| Consumption combined | 31.4 mpg |
| CO2 emission | 214 g/km |
| CO2 label | K |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-08-04 |
| Pictures | 18 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-03-27 |
| MOT pass rate | 79 % |
| MOT passed | 15 |
| Failed MOT tests | 4 |
| Total advice items | 23 |
| Total items failed | 5 |

| | |
|------------------|--|
| MOT #19 | 2023-03-28 08:34 |
| MOT test number | 242232022801 |
| Result | ✓ Passed |
| Next expiry date | 2024-03-27 |
| Advice | Offside Front Wheel bearing has slight play (5.1.3 (a) (i)) |
| Advice | Nearside Front Wheel bearing has slight play (5.1.3 (a) (i)) |

| | |
|-----------------|--|
| MOT #18 | 2023-03-22 14:14 |
| MOT test number | 894894013761 |
| Result | ✗ Failed |
| Fail | Nearside Rear Inner Tyre has a tear, caused by separation or partial failure of its structure side wall (5.2.3 (d) (ii)) |
| Advice | Offside Front Wheel bearing has slight play (5.1.3 (a) (i)) |
| Fail | Offside Front Inner Tyre has a tear, caused by separation or partial failure of its structure side wall (5.2.3 (d) (ii)) |
| Advice | Nearside Front Wheel bearing has slight play (5.1.3 (a) (i)) |

**MOT #17**

2022-02-17 12:28

MOT test number

425472927576

Result

✓ Passed

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Central Exhaust mounting defective (6.1.2 (a))

Advice Offside Front Tyre worn close to legal limit/worn on edge Inner Edge (5.2.3 (e))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Minor Nearside Obligatory mirror slightly loose (3.3 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge Outer Edge (5.2.3 (e))

MOT #16

2021-02-17 16:19

MOT test number

805178653593

Result

✓ Passed

MOT #15

2020-02-18 14:17

MOT test number

562394297889

Result

✓ Passed

Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #14

2019-02-20 09:36

MOT test number

702899716830

Result

✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2019-02-20 09:36**MOT test number** 264579262494**Result** ✗ Failed**Pass with rectification** Nearside Rear Position lamp not working (4.2.1 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2018-02-20 12:32**MOT test number** 373888719244**Result** ✓ Passed**Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Offside Rear Brake hose slightly deteriorated (3.6.B.4d)**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**Advice** Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**MOT #11** 2017-02-25 16:02**MOT test number** 862320512735**Result** ✓ Passed**MOT #10** 2016-02-16 08:32**MOT test number** 842221935167**Result** ✓ Passed**Advice** Front Road wheel slightly damaged both front (4.2.A.1a)

**MOT #9** 2016-02-04 15:32**MOT test number** 707414098291**Result** ✗ Failed**Fail** Nearside Front Wheel bolt(s) missing (4.2.A.1e)**Advice** Front Road wheel slightly damaged both front (4.2.A.1a)**MOT #8** 2015-02-20 09:43**MOT test number** 407121655069**Result** ✓ Passed**MOT #7** 2014-02-17 10:04**MOT test number** 977268744077**Result** ✓ Passed**MOT #6** 2013-02-11 18:11**MOT test number** 565372343037**Result** ✓ Passed**MOT #5** 2013-02-11 14:52**MOT test number** 576922343083**Result** ✗ Failed**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #4** 2012-02-11 10:53**MOT test number** 176132142029**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



| | |
|-----------------|------------------|
| MOT #3 | 2011-02-18 11:46 |
| MOT test number | 209649241087 |
| Result | ✓ Passed |
| MOT #2 | 2010-03-26 14:00 |
| MOT test number | 163995280412 |
| Result | ✓ Passed |
| MOT #1 | 2009-03-26 15:55 |
| MOT test number | 772085089059 |
| Result | ✓ Passed |



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | LM55BTV |
| Plate since | 2019-06-29 |
| Current registration | LM55BTV |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 21 |
| First mileage registration | 2005-12-31 |
| Last registration | 2023-03-28 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2005-12-31 | 21 mi |
| Registration #2 | 2009-03-26 | 17.724 mi |
| Registration #3 | 2010-03-26 | 26.343 mi |
| Registration #4 | 2011-02-18 | 31.969 mi |
| Registration #5 | 2012-02-11 | 37.834 mi |
| Registration #6 | 2013-02-11 | 43.208 mi |
| Registration #7 | 2013-02-11 | 43.208 mi |
| Registration #8 | 2014-02-17 | 49.139 mi |
| Registration #9 | 2015-02-20 | 56.147 mi |
| Registration #10 | 2016-02-04 | 62.567 mi |
| Registration #11 | 2016-02-16 | 62.819 mi |
| Registration #12 | 2016-02-28 | 62.819 mi |
| Registration #13 | 2016-03-12 | 62.819 mi |
| Registration #14 | 2016-03-26 | 62.819 mi |
| Registration #15 | 2016-04-09 | 62.819 mi |
| Registration #16 | 2016-04-23 | 62.819 mi |
| Registration #17 | 2016-05-07 | 62.819 mi |
| Registration #18 | 2016-05-21 | 62.819 mi |
| Registration #19 | 2016-06-04 | 62.819 mi |
| Registration #20 | 2016-06-18 | 62.819 mi |
| Registration #21 | 2023-03-28 | 62.819 mi |

More info >



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1991 mm |
| Height | 1415 mm |
| Length | 4652 mm |
| Wheel base | 2690 mm |
| Kerb weight | 1665 kg |
| Max. allowed weight | 2135 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 62 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 2 |
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | 27194030699402 |