



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	CROSSLAND
Colour	White
Year of manufacture	2018
Top speed	117 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	128 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.199 cc
Cylinders	3
Fuel type	Petrol
Consumption combined	44.1 mpg
CO2 emission	117 g/km
CO2 label	C






Internet history

Entry 1

Date	2022-01-03
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-17
MOT pass rate	100 %
MOT passed	3
Failed MOT tests	0
Total advice items	15
Total items failed	0

MOT #3	2023-08-18 07:53
MOT test number	162723586350
Result	✓ Passed
Next expiry date	2024-08-17

MOT #2	2022-09-26 13:16
MOT test number	200306797998
Result	✓ Passed

- Advice** Offside Front Tyre slightly damaged wall cut (5.2.3 (d) (ii))
- Advice** Exhaust mounting defective front hangers deteriorating (6.1.2 (a))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened worn lipped (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracked (5.2.3 (d) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened worn lipped (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracked (5.2.3 (d) (ii))



MOT #12021-09-27 11:03

MOT test number432547374870

Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Exhaust mounting defective (6.1.2 (a))	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
17 August 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	17 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>First licence fee (12 months)</b>	£ 210,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29
Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 SA68ZPC
Plate since	2019-09-29
Current registration	 SA68ZPC
Plate since	2019-09-29

More info >





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	5
First mileage registration	2018-09-26
Last registration	2023-08-18
Complete history	<a href="#">See info</a>



Registration #1	2018-09-26	13 mi
Registration #2	2021-09-27	16.837 mi
Registration #3	2022-09-28	20.277 mi
Registration #4	2023-05-29	25.277 mi
Registration #5	2023-08-18	26.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	87%
Pedestrian	63%
Safety systems	60%
Overall rating	76%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1856 mm
Height	1609 mm
Length	4477 mm
Wheel base	2675 mm
Kerb weight	1350 kg
Max. allowed weight	1910 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	10XTA11015104 LES