



RENAULT



GY6IOMR


report date: 2024-03-29

General information

Make	RENAULT
Model	MODUS GRAND DYNAMIQUE VVT
Colour	Silver
Year of manufacture	2011
Top speed	114 mph
0 - 100 km/h	12.5 seconds
0 - 60 mph	12.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	82 kW / 112 HP / 110 BHP
Max. torque	151 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 1

Date	2022-04-08
Pictures	27
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-12-14
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	30
Total items failed	20

MOT #17	2023-12-15 19:19
MOT test number	436781822474
Result	✓ Passed
Next expiry date	2024-12-14

MOT #16	2023-11-27 18:48
MOT test number	856264335691
Result	✗ Failed
<div><div>Advice</div> Front Service brake fluctuating, but not excessively both (1.2.1 (e))</div> <div><div>Fail</div> Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))</div> <div><div>Fail</div> Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))</div> <div><div>Fail</div> Nearside Front Position lamp not working (4.2.1 (a) (ii))</div> <div><div>Fail</div> Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))</div>	

MOT #15	2023-03-04 12:41
MOT test number	132404552200
Result	✓ Passed

MOT #14	2022-03-09 15:40
MOT test number	122615050295
Result	✓ Passed

**MOT #13** 2021-11-09 14:43**MOT test number** 525217580443**Result** ✓ Passed**Advice** Unable to check centre stop lamp due to being covered**Advice** Frt subframe corroded**MOT #12** 2021-11-09 11:15**MOT test number** 667878980951**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Frt subframe corroded**Fail** Nearside Rear Seat belt buckle not functioning as intended (7.1.2 (d))**Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #11** 2020-11-16 08:26**MOT test number** 715028021455**Result** ✓ Passed**Advice** Atten n/s/r seat belt buckle**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**MOT #10** 2019-11-05 14:47**MOT test number** 387518170327**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear tyre badly worn edges**Advice** Unable to check centre stop lamp due to being covered

**MOT #9** 2019-11-05 10:47**MOT test number** 268080067870**Result** ✗ Failed**Advice** Unable to check centre stop lamp due to being covered**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**Fail** Nearside Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Central Rear Seat belt buckle not functioning as intended (7.1.2 (d))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear tyre badly worn edges**MOT #8** 2018-11-01 15:07**MOT test number** 773330904994**Result** ✓ Passed**Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt**Advice** Test carried out in wet conditions!**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside front tyre worn

**MOT #7** 2018-11-01 10:46**MOT test number** 834967778067**Result** ✗ Failed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Test carried out in wet conditions!**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords inner sidewall (5.2.3 (d) (i))**Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside front tyre worn**Fail** Nearside Rear Position lamp not working (4.2.1 (a))**MOT #6** 2017-11-03 10:45**MOT test number** 974850522608**Result** ✓ Passed**Advice** Offside Rear tyre worn outer edge**Advice** Nearside Front tyre close to limit & n/s/r**MOT #5** 2017-11-03 10:45**MOT test number** 589155075445**Result** ✗ Failed**Pass with rectification** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Rear tyre worn outer edge**Advice** Nearside Front tyre close to limit & n/s/r**Pass with rectification** Offside Windscreen washer provides insufficient washer liquid (8.2.3)

**MOT #4** 2016-10-21 11:20**MOT test number** 389352975199**Result** ✓ Passed**MOT #3** 2015-09-24 11:13**MOT test number** 143382613179**Result** ✓ Passed**Advice** 2 child seats fitted to rear**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2015-09-24 09:57**MOT test number** 345051320238**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Advice** 2 child seats fitted to rear**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front Road wheel bead rim badly distorted inner rim (4.2.A.1a)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #1** 2014-09-19 15:22**MOT test number** 846492764251**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
14 December 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	14 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-





Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-11-14
Last registration	2023-12-15
Complete history	<a href="#">See info</a>



Registration #1	2011-11-14	23 mi
Registration #2	2014-09-19	12.173 mi
Registration #3	2015-09-24	18.535 mi
Registration #4	2015-09-24	18.537 mi
Registration #5	2016-10-21	25.930 mi
Registration #6	2017-11-03	33.280 mi
Registration #7	2017-11-03	33.280 mi
Registration #8	2018-11-01	39.074 mi
Registration #9	2018-11-01	39.077 mi
Registration #10	2019-11-05	44.403 mi
Registration #11	2019-11-05	44.403 mi
Registration #12	2019-11-05	44.403 mi
Registration #13	2019-11-05	44.403 mi
Registration #14	2019-11-05	44.403 mi
Registration #15	2019-11-05	44.403 mi
Registration #16	2019-11-05	44.403 mi
Registration #17	2019-11-05	44.403 mi
Registration #18	2019-11-05	44.403 mi
Registration #19	2019-11-05	44.403 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1967 mm
Height	1586 mm
Length	4034 mm
Wheel base	2482 mm
Kerb weight	1235 kg
Max. allowed weight	1722 kg

Additional information

Fuel tank capacity	51 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D045046