






General information

Make	FIAT
Model	GRANDE PUNTO ACTIVE
Colour	Red
Year of manufacture	2009
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP	0 < 101 A
Max. torque	115 Nm at 3.000 rpm	101 - 120 ^B _C
Engine capacity	1.368 cc	121 - 140 P
Cylinders	4	141 - 165 F
Fuel type	Petrol	166 - 185
Consumption city	37.7 mpg	186 - 225
Consumption extra urban	56.5 mpg	225+
Consumption combined	47.9 mpg	
CO2 emission	139 g/km	
CO2 label	E	








Internet history

Entry 4	
Date	2022-01-28
Pictures	14
Listing price	View report







source: cargurus.co.uk

Entry 3	
Date	2022-01-27
Pictures	14
Listing price	View report



source: autotrader.co.uk

Entry 2	
Date	2021-11-07
Pictures	14
Listing price	View report



source: cargurus.co.uk

Pictures

Listing price

14

View report









source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-01
MOT pass rate	93 %
MOT passed	14
Failed MOT tests	1
Total advice items	6
Total items failed	2

MOT #15	2024-02-27 09:12
MOT test number	583767919872
Result	✓ Passed
Next expiry date	2025-03-01

MOT #14	2023-02-24 10:30
MOT test number	721451366193
Result	✓ Passed
Advice Front Exhaust has a minor leak of exhaust gases flexi pipe (6.1.2 (a))	

MOT #13	2022-03-02 22:20
MOT test number	873550269173
Result	✓ Passed
Advice Suspension components slightly corroded	

MOT #12		2021-11-11 16:59
MOT test	number	867166726638
Result		✓ Passed
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))	

STO9WWX report date: 2024-03-28



MOT #11	2021-07-23 12:50
MOT test number	419161177047
Result	✓ Passed
MOT #10	2020-07-21 09:20
MOT test number	694430727954
Result	✓ Passed
MOT #9	2019-07-11 10:27
MOT test number	110629775750
Result	✓ Passed
MOT #8	2018-07-19 10:28
MOT test number	332212860177
Result	✓ Passed
MOT #7	2017-07-14 10:57
MOT test number	410145453542
Result	✓ Passed
Advice Nearside Rear tyre cracking in tread	
Advice Neurside Keur tyre cracking in tread	
MOT #6	2017-07-13 10:29
MOT test number	976421194683
Result	🗙 Failed
Fail Nearside Front Anti-roll bar linkage ball joint dust cover excessively da prevents the ingress of dirt (2.4.G.2)	amaged so that it no longer
Fail Offside Front Anti-roll bar linkage ball joint dust cover excessively dam	naged so that it no longer

prevents the ingress of dirt (2.4.G.2)

Advice Nearside Rear tyre cracking in tread





MOT #5	2016-07-06 13:44
MOT test number	870022787397
Result	✓ Passed
MOT #4	2015-07-06 09:58
MOT test number	815877485186
Result	✓ Passed
MOT #3	2014-07-14 11:51
MOT test number	999605994152
Result	✓ Passed
MOT #2	2013-07-15 10:59
MOT test number	349156693112
Result	✓ Passed
MOT #1	2012-07-23 11:11
MOT test number	306465202486
Result	✓ Passed



STO9WWX report date: 2024-03-28

Tax & MOT check

✓ Taxed	✓ MOT
Tax due: 1 March 2025	Expires: 1 March 2025
Tax status	Valid until 1 March
Days left	306
MOT expiry date	1 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4. ALANPE
Туре	
Damage 2	AMPL
	F Store
Date	1. E
Category	ame
Туре	

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



STO9WWX report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-07-30
Last registration	2024-02-27
Complete history	<u>See info</u>



Registration #1	2009-07-30	13 mi
Registration #2	2012-07-23	4.010 mi
Registration #3	2013-07-15	5.879 mi
Registration #4	2014-07-14	8.642 mi
Registration #5	2015-07-06	10.336 mi
Registration #6	2016-07-06	12.339 mi
Registration #7	2017-07-13	15.646 mi
Registration #8	2017-07-14	15.658 mi
Registration #9	2018-07-19	18.537 mi
Registration #10	2019-07-11	21.444 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 esi
Registration #18		01.777 est
Registration #19		11.777 mi
Registration #20		01.707 est





Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg
Additional information	
Fuel tank capacity	45
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles	2
Engine number	9519694