





report date: 2024-03-28

### General information

Make	CITROEN
Model	XSARA HDI EXCLUSIVE PICASSO
Colour	Silver
Year of manufacture	2003
Top speed	109 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	90 BHP
Max. torque	205 Nm at 1.900 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	61.4 mpg
Consumption combined	51.4 mpg
CO2 emission	147 g/km
CO2 label	F



CarCheck.co.uk page 1/12



# Internet history

### Entry 1

Date 2021-07-16

Pictures 25

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2022-06-29
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	5
Total items failed	8

MOT #21	2021-06-30 12:41
MOT test number	147964095052
Result	<b>✓</b> Passed
Next expiry date	2022-06-29
Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #20	2021-06-30 07:32
MOT test number	478386956365
Result	<b>X</b> Failed
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Fail  Tyre has a tear, caused by separation or partial failure of its structure Both front  (ii))	and O S R (5.2.3 (d)
Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #19	2020-09-16 09:51
MOT test number	438049854746
Result	<b>✓</b> Passed
MOT #18	2019-09-13 10:09
MOT test number	234206040566
Result	✓ Passed

CarCheck.co.uk page 3/12



LR530YL

report date: 2024-03-28

MOT #17		2019-09-13 10:09
MOT test number		795250823300
Result		<b>X</b> Failed
Pass with rectification	Windscreen washer not working (3.5 (a))	

MOT #16	2018-09-03 11:14
MOT test number	764008248528
Result	✓ Passed
MOT #15	2018-09-03 09:31
MOT test number	871214467860
Result	<b>X</b> Failed
Fail Front Windscreen washer not working (3.5 (a))	
Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))	

MOT #14	2017-09-08 09:18
MOT test number	750189080293
Result	✓ Passed
MOT #13	2016-09-02 08:34
MOT test number	251210141247
Result	✓ Passed
MOT #12	2015-09-07 10:01
MOT test number	812021242767
Result	✓ Passed
MOT #11	2014-09-18 15:12
MOT test number	668031664235
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/12



LR530YL

report date: 2024-03-28

MOT #10		2014-09-18 11:42
MOT test number		777401264264
Result		<b>×</b> Failed
<b>Notice</b> Wiper bla	ades smearing	
<b>Fail</b> Offside Fron (4.1.D.1a)	t Tyre has a cut in excess of the requirements de	eep enough to reach the ply or cords
<b>Notice</b> Nearside	rear tyre showing signs of perishing	

(4.1.D.1a)	
Notice Nearside rear tyre showing signs of perishing	3
MOT #9	2013-09-24 09:54
MOT test number	316957163414
Result	✓ Passed
MOT #8	2012-09-17 08:57
MOT test number	326981262267
Result	<b>✓</b> Passed
MOT #7	2011-09-20 09:54
MOT test number	967563461205
Result	<b>✓</b> Passed
MOT #6	2010-09-29 10:19
MOT test number	520932470208
Result	✓ Passed
MOT #5	2009-09-29 09:53

MOT #5	2009-09-29 09:53
MOT test number	251682179254
Result	✓ Passed
Advice Rear Exhaust has part of the system slightly deteriorated (7.1.1a)	

CarCheck.co.uk page 5/12



LR530YL

report date: 2024-03-28

MOT #4		2008-09-26 09:56
MOT test number		920840078268
Result		✓ Passed
MOT #3		2008-09-26 09:56
MOT test number		130330778279
Result		<b>x</b> Failed
Pass with rectification	Offside Headlamp aim too high (1.8)	
Pass with rectification	Nearside Headlamp aim too high (1.8)	

MOT #2	2007-09-27 10:04
MOT test number	301750177496
Result	✓ Passed
MOT #1	2006-09-27 10:52
MOT test number	573770876248
Result	✓ Passed


CarCheck.co.uk page 6/12



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e mier meeory	
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
manus .	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	NK NK
Flate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combont info	

**Contact info** 


 $\quad \text{More info} \quad > \quad$ 

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2003-09-30
Last registration	2021-06-30
Complete history	See info



Registration #1	2003-09-30	26 mi
Registration #2	2006-09-27	8.717 mi
Registration #3	2007-09-27	13.342 mi
Registration #4	2008-09-26	15.268 mi
Registration #5	2009-09-29	16.943 mi
Registration #6	2010-09-29	18.014 mi
Registration #7	2011-09-20	18.719 mi
Registration #8	2012-09-17	19.448 mi
Registration #9	2013-09-24	20.392 mi
Registration #10	2014-09-18	21.281 mi
Registration #11	2014-09-18	21.282 mi
Registration #12		71.777 es
Registration #13		9.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		0.074
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		71.777 es

More info >

CarCheck.co.uk page 11/12



## Safety ratings

NCAP rating

**Video** <u>see crash video</u>

## Dimensions & weight

Width	1752 mm
Height	1625 mm
Length	4267 mm
Wheel base	2760 mm
Kerb weight	1300 kg

## Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	DYLP3037355

CarCheck.co.uk page 12/12