



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	207 VERVE
Colour	Black
Year of manufacture	2009
Top speed	106 mph
0 - 60 mph	15.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	118 Nm at 3.300 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.8 mpg
CO2 emission	150 g/km
CO2 label	F





Internet history

Entry 2

Date	2021-09-01
Pictures	9
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-09-07
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	31
Total items failed	8

MOT #16	2023-09-08 12:05
MOT test number	653056892356
Result	✓ Passed
Next expiry date	2024-09-07

MOT #15	2023-09-08 10:32
MOT test number	105692303690
Result	✗ Failed
<b>MAJOR</b> Front Windscreen washer not working (3.5 (a))	
<b>MAJOR</b> Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt clip missing (6.1.7 (g) (ii))	

MOT #14	2022-09-02 09:27
MOT test number	161623035665
Result	✓ Passed
<b>Advice</b> Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>Minor</b> Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
<b>Advice</b> Offside Rear Service brake binding but not excessively (1.2.1 (f))	
<b>Minor</b> Offside Front Outer Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))	

**MOT #13** 2022-09-02 09:27**MOT test number** 510708027329**Result** ✗ Failed

- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Pass with rectification** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Front Outer Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Pass with rectification** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #12** 2021-08-31 13:26**MOT test number** 382450726034**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2021-08-27 08:38**MOT test number** 247799461614**Result** ✗ Failed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #10** 2020-08-29 13:37**MOT test number** 451429229440**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2019-08-24 13:47**MOT test number** 351506731519**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Direction Indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Direction Indicator slightly discoloured (4.4.3 (a))**MOT #8** 2018-08-04 13:36**MOT test number** 879408629841**Result** ✓ Passed**Advice** Nearside Front tyre wearing on outer edge of tyre**Advice** Offside Front Drag link end ball joint has slight play (2.1.3 (b) (i))**Advice** Nearside Rear tyre perished sidewall**Advice** Nearside Front Drag link end ball joint has slight play (2.1.3 (b) (i))**MOT #7** 2017-08-09 12:57**MOT test number** 258301637373**Result** ✓ Passed

**MOT #6** 2017-08-01 09:13**MOT test number** 573693937606**Result** ✗ Failed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)
- Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
- Pass with rectification** Nearside Stop lamp not working (1.2.1b)
- Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

**MOT #5** 2016-08-03 08:20**MOT test number** 536538533906**Result** ✓ Passed**MOT #4** 2015-07-13 16:54**MOT test number** 298324995429**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #3** 2014-07-21 15:16**MOT test number** 917902704292**Result** ✓ Passed

- Notice** Tail box bracket breaking off



MOT #2	2013-07-18 18:49
MOT test number	207239993433
Result	✓ Passed

  

MOT #1	2012-07-23 13:02
MOT test number	569765202288
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
7 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	7 September 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-28
Current registration	*****
Plate since	2023-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-07-31
Last registration	2023-09-08
Complete history	<a href="#">See info</a>



Registration #1	2009-07-31	26 mi
Registration #2	2012-07-23	7.462 mi
Registration #3	2013-07-18	15.560 mi
Registration #4	2014-07-21	22.641 mi
Registration #5	2015-07-13	29.856 mi
Registration #6	2016-08-03	38.216 mi
Registration #7	2017-08-01	45.779 mi
Registration #8	2017-08-09	45.779 mi
Registration #9	2018-08-04	49.246 mi
Registration #10	2019-08-04	52.713 mi
Registration #11	2020-08-04	56.180 mi
Registration #12	2021-08-04	59.647 mi
Registration #13	2022-08-04	63.114 mi
Registration #14	2023-08-04	66.581 mi
Registration #15	2024-08-04	70.048 mi
Registration #16	2025-08-04	73.515 mi
Registration #17	2026-08-04	76.982 mi
Registration #18	2027-08-04	80.449 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1972 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1213 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	FST36005359