





report date: 2024-03-28

### General information

Make	LAND ROVER
Model	DEFENDER PU TDI 95
Colour	Green
Year of manufacture	1994
Gearbox	-Manual

# Engine & fuel consumption

Power	111 BHP
Engine capacity	2.495 сс
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/15



report date: 2024-03-28

# Internet history

### Entry 1

Date 2021-09-11

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-28

MOT history	M	OT	history
-------------	---	----	---------

MOT expiry date	2022-04-05
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	23
Total items failed	15
MOT #21	2021-03-31 08:53
MOT test number	868650137284
Result	<b>√</b> Passed
Next expiry date	2022-04-05
MOT #20	2020-04-06 10:53
MOT test number	635943717269
Result	<b>✓</b> Passed

MOT #19	2019-03-05 16:28
MOT test number	189122285222
Result	<b>✓</b> Passed

MOT #18	2018-03-16 15:37
MOT test number	672247728694
Result	✓ Passed

MOT #17	2017-03-03 12:24
MOT test number	374358365367
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/15



report date: 2024-03-28

MOT #16		2016-02-18 09:45
MOT test	number	652920451666
Result		✓ Passed
MOT #15		2015-02-06 13:13
MOT test	number	349847135053
Result		✓ Passed
MOT #14		2014-03-04 07:56
MOT test	number	719173964052
Result		✓ Passed
Advice	Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)	
Advice	Nearside Panhard rod has slight play in a pin/bush (2.4.G.2)	
Notice	Swivels weeping	
Advice	Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)	
Advice	Coil spring corroded (2.4.C.1b)	

MOT #13	2014-03-03 17:55
MOT test number	335252764010
Result	<b>X</b> Failed
Advice Nearside Panhard rod has slight play in a pin/bush (2.4.G.2)	
Fail Rear fog lamp not working (1.3.2b)	
Advice Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)	
Advice Coil spring corroded (2.4.C.1b)	
Advice Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)	
Notice Swivels weeping	

CarCheck.co.uk page 4/15



report date: 2024-03-28

MOT #12 2013-02-18 14:14

**MOT test number** 355149543012

**MOT #11** 2013-02-18 10:25

MOT test number 636119343028

**Result** X Failed

Fail Rear Exhaust has a major leak of exhaust gases (7.1.2)

**Fail** Offside Windscreen wiper blade insecure (8.2.2)

Fail Nearside Windscreen wiper blade insecure (8.2.2)

MOT #10 2012-02-22 14:26

MOT test number 595753152082

**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #9 2012-02-22 09:52

MOT test number 119783952092

**Result** X Failed

**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)

**Fail** Offside Rear position lamp(s) not working (1.1.A.3b)

**Fail** Offside Front Body or chassis has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)

**Fail** Nearside Front Body or chassis has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)

MOT #8 2011-02-23 12:29

MOT test number 477844051046

Result 

Passed

CarCheck.co.uk page 5/15



report date: 2024-03-28

MOT #7 2011-02-23 09:40

MOT test number 488894851067

Result

× Failed

**Fail** Offside Front Body or chassis has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)

Fail

Offside Rear position lamp(s) not working (1.1.A.3b)

MOT #6 2010-02-25 09:33

MOT test number 153696150060

Result \( \sqrt{Passed} \)

**Advice** 

Exhaust has a minor leak of exhaust gases (7.1.2)

Advice

Direction indicators slightly discoloured (1.4.A.2f)

MOT #5 2009-02-25 15:22

**MOT test number** 960276459017

**Result** ✓ Passed

CarCheck.co.uk page 6/15



report date: 2024-03-28

**MOT #4** 2009-02-25 11:08 **MOT** test number 103376959021 Result **X** Failed Fail Nearside Front Brake pipe excessively corroded (3.6.B.2c) Fail Nearside Rear Brake pipe excessively corroded (3.6.B.2c) **Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f) **Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f) Offside Front Brake pipe excessively corroded (3.6.B.2c) Fail **Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2) Fail Offside Front Brake pipe excessively corroded (3.6.B.2c) Fail Offside Rear Brake pipe excessively corroded (3.6.B.2c) **Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f) Windscreen washer provides insufficient washer liquid (8.2.3) **Fail** Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

MOT #3	2008-02-19 09:58
MOT test number	340150058040
Result	<b>✓</b> Passed
Notice All brake pipes have slight corrosion	

MOT #2		2007-02-15 12:59
MOT test number		631646147037
Result		<b>✓</b> Passed
Advice Front Ex	haust has part of the system slightly deteriorated (7.1.1a)	

CarCheck.co.uk page 7/15



report date: 2024-03-28

MOT test number

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 8/15



report date: 2024-03-28

### Tax & MOT check





Tax status	Expired at 13 September
------------	-------------------------

Days left 958 days too late

MOT expiry date 5 April 2022

Full MOT history See MOT history

CarCheck.co.uk page 9/15



report date: 2024-03-28

### Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

### Damage 1

Date
Category

Damage 2

**Type** 

Date

Category

**Type** 



### Extra LAND ROVER salvage check



CarCheck.co.uk

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

page 10/15



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 11/15



factor scincol

L365PWX

report date: 2024-03-28

# For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this LAND ROVER had different number plates.

More info >

CarCheck.co.uk page 12/15



report date: 2024-03-28

### Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	1994-03-31
Last registration	2021-03-31
Complete history	See info



Registration #1	1994-03-31	29 mi
Registration #2	2006-02-20	44.559 mi
Registration #3	2007-02-15	45.860 mi
Registration #4	2008-02-19	46.615 mi
Registration #5	2009-02-25	47.035 mi
Registration #6	2009-02-25	47.035 mi
Registration #7	2010-02-25	47.872 mi
Registration #8	2011-02-23	48.652 mi
Registration #9	2011-02-23	48.652 mi
Registration #10	2012-02-22	49.335 mi
Registration #11	2012-02-22	49.335 mi
_		
Registration #12	2013-02-18	50.081 mi
Registration #12 Registration #13	2013-02-18	50.081 mi
		50.081 mi
Registration #13		50.081 mi
Registration #13 Registration #14		50.081 mi
Registration #13 Registration #14 Registration #15		50.081 mi
Registration #13 Registration #14 Registration #15 Registration #16		50.081 mi
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17		50.081 mi
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18		50.081 mi
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19		50.081 mi
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		50.081 mi

More info >

CarCheck.co.uk page 14/15



L365PWX report date: 2024-03-28

## Additional information

Fuel delivery	Direct Injection
Number of doors	2
Number of axles	2
Engine number	16L10420A

CarCheck.co.uk page 15/15