



report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Beige
Year of manufacture	-
Top speed	125 mph
0 - 60 mph	9.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	325 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg



LABEL UNKNOWN

**MOT history**

<b>MOT #16</b>	2019-11-20 14:15
<b>MOT test number</b>	821605841430
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2020-11-19

<b>MOT #15</b>	2019-10-28 09:31
<b>MOT test number</b>	147318570891
<b>Result</b>	✗ Failed

- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Front Sub-frame likely to fail heavily corroded and parts missing (5.3.3 (b) (ii))
- Advice** Inner and outer sills corroded
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Front Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Fail** Offside Front Anti-roll bar linkage fractured (5.3.3 (b) (ii))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #14** 2018-10-25 15:38**MOT test number** 734575897816**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Inner and outer sills corroded

**MOT #13** 2018-10-22 07:56**MOT test number** 466803739976**Result** ✗ Failed

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Inner and outer sills corroded
- Fail** Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Fail** Nearside Rear Seat belt anchorage prescribed area strength or continuity significantly reduced outer wheel arch (7.1.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2017-10-23 15:09**MOT test number** 521657986838**Result** ✓ Passed

**MOT #11** 2017-10-23 09:59**MOT test number** 716467731114**Result** ✗ Failed**Fail** Front Brakes imbalanced across an axle (3.7.B.5b)**MOT #10** 2016-10-18 11:56**MOT test number** 163774113119**Result** ✓ Passed**Advice** Offside and nearside rear inner sill corrosion**Advice** Wishbone and subframe corrosion**Advice** Offside and nearside rear tyre light perish**MOT #9** 2016-10-14 10:54**MOT test number** 159414144595**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Rear Suspension component mounting prescribed area is fractured outer sill (2.4.A.3)**Advice** Wishbone and subframe corrosion**Fail** Nearside Seat belt anchorage prescribed area is excessively corroded outer sill (5.2.6)**Advice** Offside and nearside rear tyre light perish**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Offside Rear Suspension component mounting prescribed area is fractured outer sill (2.4.A.3)**Advice** Offside and nearside rear inner sill corrosion**Fail** Offside Seat belt anchorage prescribed area is excessively corroded outer sill (5.2.6)

**MOT #8** 2015-11-04 11:43**MOT test number** 792156246497**Result** ✓ Passed

**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive sills (2.4.A.3)

**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive sills (2.4.A.3)

**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #7** 2014-11-06 10:57**MOT test number** 167450014358**Result** ✓ Passed

**Advice** Seat belt anchorage prescribed area is corroded but not considered excessive (5.2.6)

**MOT #6** 2013-10-17 10:11**MOT test number** 387480393254**Result** ✓ Passed**MOT #5** 2012-10-26 14:43**MOT test number** 948060202366**Result** ✓ Passed**MOT #4** 2011-09-27 12:09**MOT test number** 589500071254**Result** ✓ Passed

**Advice** Offside Rear Suspension arm has slight play in a pin/bush (2.4.G.2)

**MOT #3** 2010-09-28 14:44**MOT test number** 302561870279**Result** ✓ Passed



MOT #2	2009-10-22 12:46
MOT test number	374825799448
Result	✓ Passed

MOT #1	2008-09-26 09:54
MOT test number	224850978272
Result	✓ Passed



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	<b>PX55YLB</b>
Plate since	2024-03-29
Current registration	<b>PX55YLB</b>
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2005-09-29
Last registration	2019-11-20
Complete history	<a href="#">See info</a>



Registration #1	2005-09-29	13 mi
Registration #2	2008-09-26	16.565 mi
Registration #3	2009-10-22	23.800 mi
Registration #4	2010-09-28	29.510 mi
Registration #5	2011-09-27	36.670 mi
Registration #6	2012-10-26	46.427 mi
Registration #7	2013-10-17	60.330 mi
Registration #8	2014-11-06	65.271 mi
Registration #9	2015-11-04	69.344 mi
Registration #10	2016-05-20	75.277 mi
Registration #11	2016-05-20	75.277 mi
Registration #12	2016-05-20	75.277 mi
Registration #13	2016-05-20	75.277 mi
Registration #14	2016-05-20	75.277 mi
Registration #15	2016-05-20	75.277 mi
Registration #16	2016-05-20	75.277 mi
Registration #17	2016-05-20	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1502 kg
Max. allowed weight	2015 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	0502162050516G