





General information

Make NIS	SAN
Model MIC	RA VISIA
Colour Whi	ite
Year of manufacture 201	.6
Top speed 106	5 mph
0 - 60 mph 13.	7 seconds
Gearbox 5 sp	beed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	110 Nm at 4.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	115 g/km
CO2 label	С







Internet history

Entry 1

Date

Pictures

Listing price

2021-01-21

26

View report







source: yesauto.com



MOT history

MOT expiry date	2024-12-24
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	21
Total items failed	7

MOT #8	2023-12-15 16:27
MOT test number	361323756826
Result	🗸 Passed
Next expiry date 2024	
Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))	

MOT #7	2023-12-15 12:36
MOT test number	246258123339
Result	× Failed
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Tpms light on	
Fail Nearside Front Headlamp aim too high (4.1.2 (a))	
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice Offside Front Tyre worn close to legal limit/worn on edge on 1.6mm bald on	inner edge (5.2.3 (e))
Fail Offside Front Headlamp aim too high (4.1.2 (a))	





MOT #6	20)22-12-08 10:27
MOT test	number	408160426694
Result		🗸 Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

MOT #5		2	022-12-07 13:20
MOT test	number		917756372771
Result			🗙 Failed
Advice	Nearside Rear T	yre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))			
Pass wit	h rectification	Headlamp aim too low both. (4.1.2 (a))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))			
Fail N	earside Front Susp	pension arm ball joint excessively worn (5.3.4 (a) (i))	

MOT #4

MOT test number

MOT test	number	611590448149
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

2021-12-15 14:29





MOT #3		2021-12-15 11:02
MOT test n	number	704168037941
Result		🗙 Failed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Ne	arside Front Hydraulic brake calliper leaking (1.1.16 (b) (i))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	

MOT #2		2020-11-27 15:38
MOT test number		944425946333
Result		✓ Passed
	Both front tyres wearing on outer edges Both rear tyres wearing on inner edges	

MOT #1	2019-06-25 13:20
MOT test number	120627542784
Result	✓ Passed



Tax & MOT check

Taxed Tax due: 1 February 2025	MOT Expires: 24 December 2024
Tax status	Valid until 1 February
Days left	278
MOT expiry date	24 December 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-07-31
Last registration	2023-12-15
Complete history	<u>See info</u>



Registration #1	2016-07-31	8 mi
Registration #2	2019-06-25	20.421 mi
Registration #3	2020-11-27	28.672 mi
Registration #4		11.117 esi
Registration #5	2021-12-15	35.409 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #7 Registration #8		10.000 mil
		00.000 est 00.000 est 00.000 est

More info >





Car features

S0225	Air conditioning
\$0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	84%
Children	79%
Pedestrian	58%
Safety systems	57%
Overall rating	75%
Video	see crash video



Dimensions & weight	
Width	1665 mm
Height	1520 mm
Length	3825 mm
Wheel base	2450 mm
Kerb weight	925 kg
Max. allowed weight	1425 kg
Additional information	
Fuel tank capacity	41
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12