





report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA
Colour	Red
Year of manufacture	2001
Gearbox	-

Engine & fuel consumption

Engine capacity	1.761 cc
Fuel type	Petrol
CO2 emission	198 g/km
CO2 label	J



CarCheck.co.uk page 1/17



report date: 2024-03-29

Internet history

Entry 1

Date 2022-01-17

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/17



Y986WRP report date: 2024-03-29

MOT history

MOT expiry date	2022-06-15
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	76
Total items failed	8

MOT #20	2022-06-15 10:56
MOT test number	519342401791
Result	X Failed
Fail Emissions not tested (8.2.1.2 (d))	
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorate	ed (6.1.7 (g) (i))
Advice Rear play in rear axle	
Fail Rear Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))	
Advice General underbody corrosion	
Fail Nearside Rear Inner Suspension component mounting prescribed area excessively significantly reducing structural strength inner sill holed by corrosion (5.3.6 (a) (i))	corroded
Advice Rear Exhaust mounting defective (6.1.2 (a))	
Minor Nearside Rear Tyre obviously under inflated (5.2.3 (I))	
Advice Parking brake has low reserve travel	
Advice Brake pipe corroded, covered in grease or other material all (1.1.11 (c))	

CarCheck.co.uk page 3/17



report date: 2024-03-29

MOT #19

MOT test number

131082389373

Result

Advice Front Coil spring corroded both (5.3.1 (b) (i))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #18

MOT test number

Result

Advice

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Offside Front Coil spring corroded (5.3.1 (b) (i))

Advice

Nearside Front Coil spring corroded (5.3.1 (b) (i))

MOT #16

MOT test number

475913486429

Result

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

CarCheck.co.uk page 4/17



report date: 2024-03-29

MOT #15 2019-05-21 10:15 **MOT test number** 216777517818 Result × Failed Fail Nearside Rear Brake pipe excessively corroded (1.1.11 (c)) Offside Rear Inner Brake pipe excessively corroded (1.1.11 (c)) Fail **Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i)) Fail Offside Rear Brake pipe excessively corroded (1.1.11 (c)) **Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

MOT #14		2018-05-2	1 09:59
MOT test	number	3249806	502129
Result		✓	Passed
Advice	Nearside Side repeater slightly discoloured (4.4.3 (a))		
Minor	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))	
Advice	Offside Rear Inner Brake pipe corroded, covered in grease or other material (1.1	.11 (c))	
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (:))	
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))		
Advice	Play in steering rack inner joint(s)		
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))		
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Offside Side repeater slightly discoloured (4.4.3 (a))		
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11	(c))	
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))		
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))		

CarCheck.co.uk page 5/17



report date: 2024-03-29

MOT #13		2017-05-17 09:10
MOT test	number	439260541628
Result		✓ Passed
Advice	Play in steering rack inner joint(s)	
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)	
Advice	Offside Rear Inner Brake pipe slightly corroded (3.6.B.2c)	
Advice (2.4.G.2)	Offside Front Suspension arm ball joint dust cover damaged, but preventing the	ingress of dirt

MOT #12		2016-05-20 14:59
MOT test	number	789023130975
Result		✓ Passed
Advice	Offside Rear Inner Brake pipe slightly corroded (3.6.B.2c)	
Advice	Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)	
Advice	Nearside Rear Inner Brake pipe slightly corroded (3.6.B.2c)	
Advice	Play in steering rack inner joints	
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	

CarCheck.co.uk page 6/17



report date: 2024-03-29

MOT #11		2015-05-20 13:40
MOT test	number	377920345132
Result		✓ Passed
Advice	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)	
Advice	Offside Track rod end ball joint has slight play (2.2.B.1f)	
Notice	Play in steering rack inner joint(s)	
Advice	Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)	
Advice	Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Notice	Oil leak	
Advice	Offside Inner Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)	

MOT #10		2014-05-19 17:42
MOT test	number	285539234469
Result		✓ Passed
Advice	Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)	
Notice	Play in steering rack inner joint(s)	
Advice	Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Advice	Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)	
Notice	Oil leak	
Advice	Offside Inner Rear Brake pipe slightly corroded (3.6.B.2c)	

CarCheck.co.uk page 7/17



report date: 2024-03-29

MOT #9	2014-05-19 17:42
MOT test number	637639134147
Result	× Failed
Advice Offside Front Anti-roll bar linkage has slight play in a ball joint	(2.4.G.2)
Notice Play in steering rack inner joint(s)	
Advice Nearside Rear Brake hose has slight corrosion to ferrules (3.6.	.B.4e)
Pass with rectification Nearside Headlamp aim too high (1.8)	
Notice Oil leak	
Advice Offside Inner Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.	.4e)

MOT #8	2013-05-16 14:24
MOT test number	907626433143
Result	✓ Passed
MOT #7	2012-05-16 14:19
MOT test number	897517532108
Result	✓ Passed
MOT #6	2011-05-17 14:31
MOT test number	469937031130
Result	✓ Passed
Notice Both front shockers damp	

CarCheck.co.uk page 8/17



system requires adjustment or repair. (3.7.B.7)

Y986WRP

report date: 2024-03-29

MOT #5 2010-05-17 13:41 **MOT test number** 341967430151 ✓ Passed Result **Advice** Offside Front Shock absorber has a light misting of oil (2.7.3) Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) **Advice** Offside Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7) Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f) Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Nearside Parking brake: parking brake efficiency only just met. It would appear that the braking

MOT #4		2009-05-18 10:45
MOT test	number	263038539416
Result		✓ Passed
Advice	Offside Front Direction indicator slightly discoloured (1.4.A.2f)	
Advice	Brake disc slightly scored (3.5.1h)	
Advice	Offside Side repeater slightly discoloured (1.4.A.2f)	
Advice requires a	Nearside Brakes imbalanced requirements only just met. It would appear that djustment or repair. (3.7.B.5b)	the braking system

MOT #3	2008-06-16 09:43
MOT test number	151368168155
Result	✓ Passed
MOT #2	2007-05-14 10:49
MOT test number	521594537177
Result	✓ Passed

CarCheck.co.uk page 9/17



report date: 2024-03-29

MOT #1 2006-04-27 16:34

MOT test number 152197516106

Result ✓ Passed

Advice

Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 10/17



report date: 2024-03-29

Tax & MOT check

Tax expired: 11 May 2022





Expired: 15 June 2022

Tax status	Expired at 11 May 2022
Days left	719 days too late
MOT expiry date	15 June 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 11/17



report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 12/17



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 13/17



report date: 2024-03-29

Owner history

e mier metery	
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full in	

manus .	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	NK SIX
Flate since	
Current registration	UK UK
Flate since	
	More info >

CarCheck.co.uk page 14/17



report date: 2024-03-29

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 15/17



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2001-05-25
Last registration	2022-06-15
Complete history	See info



Registration #1	2001-05-25	19 mi
Registration #2	2006-04-27	31.184 mi
Registration #3	2007-05-14	37.301 mi
Registration #4	2008-06-16	42.323 mi
Registration #5	2009-05-18	44.213 mi
Registration #6	2010-05-17	47.771 mi
Registration #7	2011-05-17	49.653 mi
Registration #8	2012-05-16	53.249 mi
Registration #9	2013-05-16	56.218 mi
Registration #10	2014-05-19	60.156 mi
Registration #11	2015-05-20	64.267 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.117 au
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		

More info >

CarCheck.co.uk page 16/17



Y986WRP report date: 2024-03-29

Safety ratings

NCAP rating

Video <u>see crash video</u>

Additional information

Number of seats 5

Engine number KJR42045589

CarCheck.co.uk page 17/17